



U.S. Department
of Transportation
**Federal Aviation
Administration**



SDR

Service Difficulty Reporting

December 28, 1997 - January 3, 1998 Summary

AIR CARRIER, ZAC-326

You can improve Air Safety by reporting the problem when you see it!

SECTION

- I Significant Occurrence Report
- II Domestic Service Difficulty Report
- III International Service Difficulty Report
- IV Index By Operator
- V Index By Aircraft Make and Model
- VI Joint Aircraft System/Component Code Table

ISSUE: 98-01



U.S. Department
of Transportation
**Federal Aviation
Administration**

SDR SUMMARY

Air Carrier, ZAC-326



This summary includes domestic (United States) Service Difficulty Reports (SDRs) (which are the same as mechanical reliability reports or MRRs) entered into the data base for aircraft weighing over 12,500 lbs. All helicopter are excluded from this report (see the General Aviation SDR Summary, ZAC-327). A separate section for International SDRs for aircraft weighing over 12,500 lbs. has also been included. Under a data exchange agreement, International SDRs are submitted to the FAA by the Civil Aviation Authority of other countries (currently, Canada - CAN, and Australia - AUS). All reports are sorted by aircraft make, model group (basic model), and Joint Aircraft System/Component (JASC) code. Within each aircraft model group, the specific model shown may vary, but similar types of reports will be grouped together and listed in ascending order by their JASC code. Each field contains all information submitted to the FAA. Some fields are not included in order to make the summary easier to read. Reports of significance are highlighted with a star border. Additional information may be obtained by referring to the "operator control number." Send your request to the Aviation Data Systems Branch, AFS-620 at the address or phone below.

The Regulatory Support Division (AFS-600) has established a "HomePage" on the Internet through which the same information is available. There is a large quantity of other information available through the AFS-600 HomePage such as the most current SDR system codes (i.e., Joint Aircraft System\Component Codes). The SDR Question and Answer Section of the Summary will also be transferred to the AFS-600 HomePage to simplify the process of preparing the SDR Summaries in the PDF format each week. There are "hot buttons" to take you to other locations and sites where FAA Flight Standards Service Information is available. The AFS-600 "HomePage" address is:

<http://www.mmac.jccbi.gov/afs/afs600>

“The Service Difficulty Reports in this publication are derived from unverified information submitted by the aviation community without FAA verification for accuracy. The number of SDRs submitted is not an indication of the mechanical reliability or fitness of an airline or individual operator, and the information should not be used as such.”

Comments are welcomed and may be directed to:


*Federal Aviation Administration
Aviation Data Systems Branch, AFS-620
P.O. Box 25082
Oklahoma City, OK 73125-5029
Phone: (405) 954-4171, Fax: (405) 954-4748*

Your continued participation is essential and is an integral part of ensuring aviation safety. Thank you for supporting the Service Difficulty Program! If you have any questions regarding this special notice you can contact John Jackson at (405) 954-6486, or Jim Gillespie at (405) 954-1141, or Blake McDonald at (405) 954-0307 in the Aviation Data Systems Branch (AFS-620). Their E-mail addresses are:


john_e_jackson@mmacmail.jccbi.gov

james_gillespie@mmacmail.jccbi.gov

blake_mcdonald@mmacmail.jccbi.gov



SIGNIFICANT OCCURRENCE REPORT





U.S. Department
of Transportation
**Federal Aviation
Administration**

THE SIGNIFICANT OCCURRENCE REPORT



The Significant Occurrence Report is a compilation all of the star bordered reports that appear in the Air Carrier Service Difficulty Report (SDR) Summary, ZAC-326. The Significant Occurrence Report is used to highlight industry problem areas to field inspectors and the aviation public.

Limited analysis is performed by the Aviation Data Systems Branch, AFS-620 during the preparation of the "Significant Occurrence Report", which is generated each week and is included in the front of the Air Carrier SDR Summary. Significant Reports are hand selected by AFS-620's inspectors based on the individual merit of each report. The criteria for selection includes, but is not limited to, items that indicate high failure rates; items related to accidents or incidents; or design or maintenance failures which may affect the safe operation of the aircraft.

In some cases, this limited analysis of SDR data leads to the preparation of information bulletins which are routed to the appropriate product certification office for further investigation of the problem. The end result may be the issuance of an airworthiness directive (AD) by the Aircraft Certification Service (AIR) if warranted.

The Significant Occurrence Report (section I) of the weekly SDR Summary is not intended to be a summary of all significant events and should not be used as such. We recommend that you review further the applicable sections of the SDR summary that may be of interest.

Immediately following the Significant Occurrence Reports is the Significant Occurrence Report Index. This index provides a historical perspective to the selected Significant Occurrences Reports, and can be useful in helping to identify potential trends. All SDR's with the same part number are compiled; sorted by year and aircraft model; and then the totals are calculated for each part number. Remember, the index includes part numbers of the suspect "Part" causing the problem, only if the part number is provided in the current week's star bordered SDR's.

SIGNIFICANT OCCURRENCE REPORT

12/28/97 - 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|--|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-----------------------------|-----------|----------------------------|
| 7230 | | | PWA JT9D7R4D | | PWA | COMPRESSOR BLADE | DAMAGED 8TH & 9TH STAGES | 6896 | 8/18/94 CA941004504 |
| ***** | (CAN) AFTER TAKEOFF 300 FEET THERE WAS A LOUD EXPLOSION ACCOMPANIED BY A YAW TO THE LEFT. LEFT ENGINE EGT ANNUNCIATED IN RED. ENGINE POWER REDUCED TO IDLE. FLIGHT RETURNED & LANDED WITHOUT FURTHER INCIDENT. FOUND METAL PIECES IN UPPER LEFT BLEED VALVE SCREEN ENGINE BOROSCOPE & REVEALED DAMAGE TO 8TH & 9TH STAGE COMPRESOR BLADES. | | | | | | | | |
| 7200 | 959CA | CNDAIR | GE | | | ENGINE | FAILED | | 12/22/97 |
| COMA | 7116 | CL6002B19 | CF343A1 | | | | RIGHT | | COMA9760253 |
| ***** | UNCOMMANDED ACCELERATION OF RIGHT ENGINE ALL ENGINE PARAMETERS WERE EXCEEDED. REPLACED ENGINE. | | | | | | | | |
| 8530 | | DHAV | PWA | | | CYLINDER | SEPARATED | | 9/12/97 |
| | | DHC3 | R1340* | | | 20578A1 | ENG NR 1 CYL | 611 | CA970926010 |
| ***** | (CAN) THE AIRCRAFT WAS ON DESCENT, FOR SEVERAL MINUTES, WITH REDUCED POWER, THE ENGINE BACKFIRED AND QUIT. POWER OFF LANDING CARRIED OUT ON LAKE. THE ENGINE WAS RESTARTED FOR TAXIING, BUT RAN ROUGH AND WAS SHUTDOWN. INSPECTION FOUND THE NR1 CYLINDER HEAD HAD SEPARATED THROUGH THE CENTRE WITH THE ENTIRE INTAKE VALVE HOUSING. INTAKE VALVE PIECES ENTER BLOWER DIFFUSER SECTION WITH SOME PIECES FOUND IN NR5 AND NR6 CYLINDER INDUCTION PIPES. THE EXHAUST VALVE WAS ALSO BROKEN AND POUNDED INTO A TRIANGULAR SHAPE AND REMAINED IN THE CYLINDER UPPER CHAMBER. THERE WAS HEAVY METAL CONTAMINATION THROUGHOUT THE ENGINE. THE ENGINE WAS DEEMED UNREPAIRABLE AND REMOVED. | | | | | | | | |
| 7230 | 160US | DOUG | PWA | | | COMPRESSOR | STALLED | | 12/22/97 |
| NWAA | 46769 | DC1040 | JT9D20J | | | | NR 3 ENGINE | | 9724251160 |
| ***** | DURING LANDING ROLLOUT, WHILE IN REVERSE THRUST THE NR 3 ENGINE COMPRESSOR STALLED. THE EGT ROSE TO 880C BEFORE THE ENGINE WAS SHUT DOWN. MAINTENANCE INSPECTED THE ENGINE PER MM71-00-00 WITH NO DEFECTS NOTED. THE ENGINE WAS RUN WITH NORMAL INDICATIONS. THE NR 3 THRUST REVERSER WAS PLACED ON MEL AND THE AIRCRAFT RETURNED TO SERVICE. | | | | | | | | |
| 2740 | 491US | FOKKER | | | | TRIM | MALFUNCTIONED | | 12/20/97 |
| QXEA | 11156 | F28MK4000 | | | | | HORIZ STAB | | QXEA9700917 |
| ***** | PDX- DESCENDING THROUGH 13000 FT, FIRST OFFICER DISCONNECTED THE AUTOPILOT FOR LANDING. FELT A NOSE DOWN FORCE ON THE ELEVATOR AND ATTEMPTED TO TRIM THE PRESSURE OFF WITH STABILIZER TRIM WHEEL. ALTERNATE STAB TRIM WAS TRIED BUT IT TRIPPED CIRCUIT BREAKER. THE CIRCUIT BREAKER WAS RESET AND ALTERNATE TRIM TRIED AGAIN BUT CIRCUIT BREAKER TRIPPED A SECOND TIME. FIRST OFFICER SLOWED AIRCRAFT TO ABOUT 210 KNOTS AND CONTINUED TO FLY MANUALLY. DIRECT ROUTING TO RUNWAY REQUESTED. AIRCRAFT LANDED WITHOUT INCIDENT. AIRCRAFT DOWN FOR REPAIRS. | | | | | | | | |
| 5751 | | PIPER | | | PIPER | SPAR | CRACKED | 16043 | 8/2/94 |
| | | PA31350 | | | 4020022 | 4019008 | LT AILERON | | CA940928107 |
| ***** | (CAN) SLIGHT FLEXING NOTICED BETWEEN LH AILERON INBOARD BEARING ATTACH BRACKET & AILERON SPAR. BRACKET REMOVAL SHOWED A 2 INCH CRACK IN AILERON SPAR. A 1" CRACK FOUND ON RH. | | | | | | | | |

(End of SIGNIFICANT OCCURRENCE REPORT)


Run Date: 08-Jan-98

FEDERAL AVIATION ADMINISTRATION
SIGNIFICANT OCCURRENCE REPORT INDEX


Showing Specific Part Numbers and Aircraft Model by Year

FOR THE PERIOD OF: 12/28/97 To 1/3/98


| <u>PART NUMBER</u> | | | <u>YEAR</u> | | | | | | | | | | |
|--|-------------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <u>PART NAME</u> | <u>ACFT MODEL</u> | <u>TOTAL</u> | <u>1987</u> | <u>1988</u> | <u>1989</u> | <u>1990</u> | <u>1991</u> | <u>1992</u> | <u>1993</u> | <u>1994</u> | <u>1995</u> | <u>1996</u> | <u>1997</u> |
| 20578A1 | | | | | | | | | | | | | |
| CYLINDER | DHC3 | 1 | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # 20578A1 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | 1 |
| 4019008 | | | | | | | | | | | | | |
| SPAR | PA31350 | 1 | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL of # 4019008 ----- | | 1 | - | - | - | - | - | - | - | - | - | - | 1 |
| TOTAL for ALL (2) PART NUMBERS: ----- | | 2 | - | - | - | - | - | - | - | - | - | - | 2 |
| END OF SIGNIFICANT OCCURRENCE REPORT INDEX | | | | | | | | | | | | | |



DOMESTIC



SERVICE DIFFICULTY REPORT



DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY**12/28/97 - 1/3/98 ISSUE: 98-01 ZAC-326**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---------------------|------------------------------|---------------------------------|-----------------------------|-------------------------------|------------------------------|----------------------------------|--------------------------------|-------------------|------------------------------------|
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | 18952 3058 | 7/1/96 EY2R9600900 |
| | | BEARING CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | LOW STOP COLLAR 3475A3 | CORRODED PROPELLER ASSY | | 5/1/96 EY2R9600673 |
| | | LOW STOP COLLAR FOUND CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | LOW STOP COLLAR 3475A3 | CORRODED PROPELLER ASSY | | 5/1/96 EY2R9600672 |
| | | LOW STOP COLLAR FOUND CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | | 5/1/96 EY2R9600671 |
| | | BEARING CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | BOLT 338614H | CORRODED PROPELLER ASSY | 18952 3058 | 7/1/96 EY2R9600903 |
| | | BOLT CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | BOLT 338614H | CORRODED PROPELLER ASSY | 18952 3058 | 7/1/96 EY2R9600902 |
| | | BOLT CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | 18952 3058 | 7/1/96 EY2R9600901 |
| | | BEARING CORRODED. | | | | | | | |
| 6110 | | BEECH 1900C | | HARTZL HCB4MP3 | | CYLINDER 3406 | CORRODED PROPELLER ASSY | 14107 3709 | 6/1/96 EY2R9600820 |
| | | CORROSION FOUND ON CYLINDER. | | | | | | | |
| 6111 | | BEECH 1900C | | HARTZL HCB4MP3 | | BLADE M10476 | CORRODED PROPELLER ASSY | | 5/1/96 EY2R9600674 |
| | | BLADE FOUND CORRODED. | | | | | | | |
| 6114 | | BEECH 1900D | | HARTZL HCE4A3A | | HUB 3932 | CORRODED PROPELLER ASSY | | 9/1/96 EY2R9601007 |
| | | HUB CORRODED. | | | | | | | |
| 6110 | | BEECH 300BEECH | | HARTZL HCB4MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | | 6/1/96 EY2R9600821 |
| | | BEARING CORRODED. | | | | | | | |

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------------|-----------|----------------------------|
| 2612 FDEA | 278FE 22345 | BOEING 727233 | | | | BULB | FAILED NR 2 FIRE DET | | 12/23/97 97FDEA00901 |
| ON CLIMBOUT, THE LOWER AFT BODY OVERHEAT LIGHT ILLUMINATED. CHECK LIST WAS RUN. SOURCE OF OVERHEAT APPEARED TO BE NR 2 ENGINE INLET AND COWL ANTI-ICE SYSTEM. CHECKED ALL FIRE LOOPS, FOUND NO PROBLEMS. CLOSED UP AFT AIRSTAIRS, RAN BOTH PACKS TO HEAT UP AIR STAIR AREA DID NOT GET A LIGHT. FOUND THE BULB CONTACT WELDED TO SOCKET. REMOVED AND REPLACED BULB. NO PREVIOUS HISTORY OF WRITE UPS ON THIS PROBLEM. | | | | | | | | | |
| 2613 IPXA | 950UP 19718 | BOEING 72725C | | | | OVERHEAT LOOP | OUT OF POSITION NR 1 STRUT | | 12/24/97 UPS97225359 |
| INSPECTION TYPE-N/A, ENG NR 1 STRUT OVHT LIGHT ILLUMINATED. IN CRUISE AT FL 290 ENG PARS EPR 1.620 ENG TAT ON AND THRUST STABLE FOR APPX 15 MIN. CHKLST WAS FOLLWED AND THRUST WAS REDUCED AND ENG 1 BLEED CB WAS PULLED. AFTER WAITING 3 MINS THE LIGHT STAYED ON SO THE NR 1 ENG WAS SHUTDOWN. THE LIGHT STAYED ON FOR ANOTHER 4 TO 5 MINS, THEN WENT OUT. RAN ENGS TO 1.7EPR FOR 20 MINS ON GROUND. OPENED ALL ACCESS PANELS, CHKD FOR AIR LEAKS AND FOR SENSING LOOP GNDING OUT, FOUND ALL OK. COULDN'T FIND ANY FAULTS. REPOSITIONED SEVERAL GROMMENTS AT SENSING LOOP. OPS CHK OK ON GROUND. | | | | | | | | | |
| 2782 DALA | 417DA 21259 | BOEING 727232 | | | | BRACKET | CRACKED NR 1 SLAT ACT | | 12/22/97 DL72K972706 |
| FOUND ON B2 LETTER CK, 1 INCH VISIBLE CRACK NR 1 SLAT ACTUATOR O/B ATTACH BRACKET. REPAIRED PER MM 57-20-21. | | | | | | | | | |
| 2782 FDEA | 235FE 21329 | BOEING 727247 | | | | ACTUATOR 26900297 | FAILED NR 2 LE SLAT | | 12/23/97 97FDEA00899 |
| 97-0256 AFTER TAKEOFF FLAPS WERE RETRACTED TO 0 DEG AND AMBER LE FLAPS LIGHT REMAINED ILLUMINATED ON FORWARD INSTRUMENT PANEL. S/O PANEL CONFIRMED NR 2 SLAT EXTEND. CYCLED FLAPS SEVERAL TIMES BOTH LIGHTS WOULD GO OUT MOMENTARY AND THEN REILLUMINATED. REF OIL NR 27-80-2061. REMOVED AND REPLACED NR 2 SLAT ACTUATOR PER M/M REF 27-81-32. | | | | | | | | | |
| 2910 DALA | 535DA 22048 | BOEING 727232 | | | | TUBE 6517840290 | BROKEN NR 2 LE SLAT | | 12/19/97 DL72S972680 |
| ON TAXI OUT, -A- SYS HYD FAILED. REPLACED NR 2 L/E SLAT LINE. | | | | | | | | | |
| 3260 K3HA | 356PA 20626 | BOEING 727225 | | | | CONNECTOR 696R10SL35 | SHORTED NLG | | 12/24/97 K3HA9700143 |
| ON APPROACH, UNSAFE LIGHT CAME ON AND STAYED ON AFTER NOSE GEAR WAS DOWN AND LOCKED. FOUND PLUG ON LOCK SWITCH S93 SHORTED. REPLACED PLUG AND WIRED TO SYSTEM, CHECKS OK PER WDM 32-60-02. | | | | | | | | | |
| 3260 DHLA | 705DH 19191 | BOEING 72722C | | | | UNSAFE LIGHT | ILLUMINATED RT MLG | | 12/24/97 DHL97705006 |
| UPON GEAR EXTENSION, RIGHT GEAR RED UNSAFE LIGHT ILLUMINATED WITH NOSE AND LT GEAR SAFE LIGHT ON. WITH GO-AROUND AND MANEUVERING HAD INTERMITTENT RED AND GREEN RT GEAR LIGHT. UPON MANUAL GEAR EXTENSION FOR RIGHT HAND GEAR HAD GREEN SAFE LIGHT INDICATION PRIOR TO LANDING. JACKED AIRCRAFT AND CYCLED GEAR 7 TIMES, NO DEFECTS NOTED. | | | | | | | | | |
| 3350 K3HA | 354PA 20624 | BOEING 727225 | | | | BULB 3071 | FAILED CABIN | | 12/26/97 K3HA9700144 |
| EMERGENCY PATH LIGHTING ONE LIGHT INOP ROW 23DEF. RELAMPED, OPS CHECKS GOOD IAW B727 MM 33-59-00. | | | | | | | | | |
| 3350 K3HA | 8883Z 21580 | BOEING 727225 | | | | BATT CHARGER 110049 | FAILED CABIN | | 12/26/97 K3HA9700145 |
| AT POST FLIGHT INSPECTION, FOUND EMEGENCY PATH LIGHTING BATTERY CHARGER AT FWD LIFE RAFT STORAGE COMPARTMENT INOP. REMOVED AND REPLACED EMERGENCY PATH LIGHTING BATTERY CHARGER REF MM 33-50-22, OPS CHECK OK. | | | | | | | | | |
| 3350 DALA | 474DA 20751 | BOEING 727232 | | | 900835A | BATTERY | DISCHARGED LT WING | | 12/27/97 DL72K972733 |
| FWD LT WING OUTSIDE EMERG LIGHT INOP. REPLACED BATTERY, CKS OK. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--------------|---|-------------------------|---------------------|-----------------------|----------------------|--------------------------|-------------------------|-----------|----------------------------|
| 3350 DALA | 479DA 20756 | BOEING 727232 | | | 3114981 | LIGHT | INOPERATIVE R2 DOOR | | 12/25/97 DL72K972727 |
| | R2 EMERG SLIDE LIGHT INOP. REPLACED REFLECTOR, OPS CHKS GOOD. | | | | | | | | |
| 3350 DALA | 531DA 21814 | BOEING 727232 | | | | BATTERY S106 | DISCHARGED CABIN | | 12/24/97 DL72S972726 |
| | EMERG LIGHT ABOVE AFT AIRSTAIRS INOP. REPLACED BATTS AND CKS GOOD. | | | | | | | | |
| 3350 DALA | 537DA 22073 | BOEING 727232 | | | | BATTERY PACK 900835A | DISCHARGED CABIN | | 12/27/97 DL72S972734 |
| | CENTER AISLE EMER EXIT LIGHT INOP. REPLACED BATTERY PACK, OPS NML. | | | | | | | | |
| 3610 FDEA | 490FE 21493 | BOEING 727227 | | | | DUCT 652244419 | FAILED NR 1 PYLON | | 12/23/97 97FDEA00898 |
| | 97-0255 - DURING TAKEOFF WITH CLIMB POWER SET NR 1 STRUT OVERHEAT LIGHT CAME ON. PULLED THRUST ON NR 1 BACK TO 80 PERCENT N1, NR 1 BLEED OPEN LEFT PACK ON LIGHT GOES OUT. FOUND 8TH STAGE DUCT LEAKING AT FLANGE WELD. REPLACED DUCT JUST OUT BOARD OF PYLON ON THE ENGINE. LEAK CHECKED AT IDLE, LEAK CHECK NORMAL. NEEDS HIGH POWER RUN. | | | | | | | | |
| 5310 DALA | 417DA 21259 | BOEING 727232 | | | | STRUCTURE | CRACKED BS 1263-1273 | | 12/23/97 DL72K972719 |
| | THE RT TORQUE BOX STRUCTURE IN THE VENTRAL STAIRWAY WAS FOUND TO THREE CRACKED MEMBERS. THE FS 1263 BEAM WAS FOUND WITH A 1.0 CRACK AND THE FS 1273 BEAM AND GUSSET WERE FOUND WITH 1.0 CRACKS. THE DAMAGED MEMBERS WERE REPLACED PER BAC S/B 727-53-0129 AS DOCUMENTED IN ER/A 363537-14AD. | | | | | | | | |
| 5311 DALA | 403DA 21147 | BOEING 727232 | | | | FRAME | DENTED BS 1030 | | 12/20/97 DL72S972714 |
| | FRAME DENTED FS 1030 AT STR 26L. REPAIRED PER SRM 53-10-4 FIG 27. | | | | | | | | |
| 5312 DALA | 503DA 21305 | BOEING 727232 | | | | BLKHD STIFFENER | CRACKED FS 1183 | | 12/18/97 DL72L972681 |
| | A 2 INCH CRACK WAS FOUND IN THE RBL 36.83 STIFFENER AND A 1 INCH CRACK WAS FOUND IN THE LBL 36.83 STIFFENER AT WL 238 ON THE FS 1183 BULKHEAD. THE STIFFENERS WERE REPAIRED PER BOEING S/B 727-53-0192 AS DOCUMENTED IN ER/A 363498-14. | | | | | | | | |
| 5313 DALA | 417DA 21259 | BOEING 727232 | | | | STRINGER | CRACKED BS 942 | | 12/22/97 DL72K972717 |
| | A 1.5 INCH CRACK IN LWR RADIUS OF STR 18A. REPAIRED PER MM 53-12-0 PG 820. | | | | | | | | |
| 5320 KT3R | 352PA 20616 | BOEING 727225 | | | | SUPPORT | CORRODED BS 420-440 | | 11/1/97 97ZZZX4987 |
| | DURING C-CHECK, CORROSION NOTED ON CABIN FLOOR SUPPORT BETWEEN STA 420 - STA 440 AT RBL 12. | | | | | | | | |
| 5320 DALA | 499DA 21143 | BOEING 727232 | | | | WEB | CRACKED BS 1223 | | 12/23/97 DL72S972713 |
| | A 1 INCH CRACK IN LIGHTENING HOLE TORQUE BOX WEB RT SIDE STA 1223. REPAIRED PER MM 53-11-0 PG 828. | | | | | | | | |
| 5320 DALA | 526DA 21586 | BOEING 727232 | | | | TORQUE BOX 65175186 | CRACKED BS 1273 | | 12/17/97 DL72S972694 |
| | WHILE ACCOMPLISHING THE TORQUE BOX INSPECTIONS PER B727 S/B 53-0129 AS MANDATED BY AD 94-07-08, THE FS 1273 BEAM AND GUSSET WERE FOUND CRACKED. THE DAMAGE PARTS WERE REPLACED PER THE S/B AND DOCUMENTED PER ER/A 363483-14AD. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------------|-----------|----------------------------|
| 5330 DALA | 468DA 20745 | BOEING 727232 | | | | SKIN | CORRODED BS 600 | | 12/19/97 DL72S972699 |
| THE FUSELAGE SKIN WAS FOUND CORRODED AT THE STRINGER 26L LAPSPLICE BETWEEN FS 575 AND 613. THE CORRODED AREA WAS CUTOUT AND A REPAIR DOUBLER INSTALLED. AREAS FWD AND AFT OF THE CUTOUT WERE INSPECTED TO ENSURE NO FURTHER CORROSION WAS PRESENT. THE REPAIR WAS ACCOMPLISHED PER ER/A 363462-14. | | | | | | | | | |
| 5330 DALA | 417DA 21259 | BOEING 727232 | | | | SKIN | CRACKED L 1 DOORWAY | | 12/22/97 DL72K972705 |
| FOUND DURING B-2 LETTER CHECK, 1.25 INCH CRACK FUSELAGE SKIN AT MAIN ENTRY DOOR UPPER HINGE CUTOUT. REPAIRED PER SRM 53-30-3 FIG 33, TIME LIMITED. | | | | | | | | | |
| 5330 DALA | 503DA 21305 | BOEING 727232 | | | | SKIN 65545905 | CORRODED BS 700 | | 12/19/97 DL72L972697 |
| THE FUSELAGE SKIN A FS 705, BL 0 WAS FOUND WITH A SMALL AREA OF CORROSION. THE DAMAGE WAS REMOVED WITH A 1 DIA HOLE. THREE OTHER REPAIRS WERE IN THE GENERAL AREA OF THE CUTOUT. THEREFORE, THE SKIN WAS CUT AT FS 710 FROM S-26L TO S-26R AND A NEW SECTION OF SKIN WAS SPLICED IN PER ER/A 363516-14. | | | | | | | | | |
| 5330 DALA | 506DA 21308 | BOEING 727232 | | | | SKIN | CORRODED BS 1050 | | 12/19/97 DL72L972693 |
| THE FUSELAGE SKIN WAS FOUND CORRODED AT STA 1050, S-29R. THE SKIN WAS CUTOUT WITH A 1 X 4 CUTOUT. THE DAMAGE WAS ADJACENT TO A PREVIOUSLY INSTALLED SKIN REPAIR. THE EXISTING REPAIR WAS REMOVED AND A NEW DOUBLER INSTALLED TO INCORPORATE BOTH REPAIR AREAS. THE DOUBLER WAS INSTALLED PER THE GUIDELINES OF THE B727 SRM AND DOCUMENTED PER ER/A 363508-14. | | | | | | | | | |
| 5414 DALA | 471DA 20748 | BOEING 727232 | | | | SKIN | CRACKED S-DUCT HOUSING | | 12/19/97 DL72K972685 |
| FOUND ON B2 LETTER CK, SEVERAL 1 INCH CRACKS 'S' DUCT HOUSING FWD OF ACCESS PANEL 9501 LT LOWER CORNER. REPAIRED PER MM 54-30-0. | | | | | | | | | |
| 5414 DALA | 417DA 21259 | BOEING 727232 | | | | SKIN | CRACKED S-DUCT HOUSING | | 12/22/97 DL72K972707 |
| FOUND ON B2 LETTER CK, SEVERAL .25 INCH CRACKS 'S' DUCT HOUSING FWD OF ACCESS PANEL 9501 RT SIDE. REPAIRED PER MM 54-30-0. | | | | | | | | | |
| 5720 DALA | 414DA 21256 | BOEING 727232 | | | | BRACKET | MISINSTALLED NR 1 LE SLAT | | 12/21/97 DL72K972700 |
| WHILE ACCOMPLISHING INSPECTIONS MANDATED BY DAL SI 4-59271-12AD, MTC FOUND A .031 GAP BETWEEN THE NR 1 SLAT ACTUATOR AND THE SUPPORT FITTINGS. THE GAP WAS SHIMMED PER THE REQUIREMENTS OF BAC S/B 727-57-0130 AND DOCUMENTED IN ER/A 363526-14AD. | | | | | | | | | |
| 5754 DALA | 417DA 21259 | BOEING 727232 | | | | RIB | CRACKED NR 7 LE SLAT | | 12/22/97 DL72K972708 |
| FOUND ON B2 LETTER CHECK, 1.25 INCH CRACK IN RADIUS OF NOSE RIB I/B SIDE OF ACTUATOR ATTACH NR 7 SLAT. REPAIRED PER MM 57-54-0. | | | | | | | | | |
| 5754 DALA | 510DA 21312 | BOEING 727232 | | | 651622268 | RIB | CRACKED NR 6 LE FLAP | | 12/13/97 DL72L972678 |
| RIB NR 18 CRACKED. REPAIRED PER MM 57-54-0. | | | | | | | | | |
| 7312 FDEA | 492FE 21530 | BOEING 727227 | | | | HEAT VALVE | MALFUNCTION NR 1 ENGINE | | 12/23/97 97FDEA00897 |
| 97-0254 - NR 1 ENGINE OIL TEMPERATURE IN YELLOW BAND DUE TO FUEL HEAT VALVE STUCK OPEN. SHUTDOWN ENGINE, AFTER 15 MINUTES TEMPERATURE AT 125C MAX TEMPERATURE 130C LESS THAN 5 MINUTES. WINDMILL 50 MINUTES. PULLED OIL FILTER, FOUND CLEAN. INSTALLED NEW FILTER, MOTORED ENGINE NO LEAKS NOTED. REPLACED FUEL DE-ICING VALVE PER MAINTENANCE MANUAL 73-14-11. CANNON PLUG TO THE VALVE IS BAD AND NEEDS TO BE CHANGED. THE VALVE REMAINS DEFERRED PLUG REMOVED, BAGGED AND TIED BACK. VALVE IS WIRED IN THE CLOSED POSITION. CIRCUIT BREAKER OPENED AND COLLARED. | | | | | | | | | |

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|---------------------------------|------------------------|-----------|----------------------------|
| 7314 FDEA | 287FE 21849 | BOEING 7272D4 | PWA JT8D7B | | | FUEL PUMP 378200 | FAILED NR 1 ENGINE | | 12/23/97 97FDEA00900 |
| 97-0257 - NR1 ENGINE FAILURE AT 400 FEET ABOVE GROUND LEVEL. POP HEARD IN COCKPIT. ENGINE WINDMILLED WITH NORMAL INDICATIONS. RESTART UNSUCCESSFUL. FOUND INPUT SHAFT FOR FUEL PUMP SPLINES STRIPPED INSIDE PUMP. REMOVED AND REPLACED NR 1 ENGINE FUEL PUMP PER MAINTENANCE MANUAL 73-11-01, AND REMOVED AND REPLACED FUEL CONTROL PER MAINTENANCE MANUAL 73-20-01. INSPECTED INLET AND EXHAUST, NO DEFECTS FOUND. NR 1 ENGINE LEAK AND OPERATIONAL CHECK GOOD. PERFORMED TAKEOFF EPR CHECK PER JET RUN HANDBOOK 6-15, CHECK GOOD. | | | | | | | | | |
| 7930 DALA | 532DA 22045 | BOEING 727232 | | | 39302001789 | INDICATOR 39302001789 | FAILED NR 3 ENGINE | | 12/22/97 DL72S972702 |
| SMOKE IN THE COCKPIT, FLT DIVERTED TO BHM. MTC FOUND NR 3 ENG OIL QTY IND TO BE SOURCE OF SMOKE. REPLACED INDICATOR. | | | | | | | | | |
| 7931 DHLA | 720DH 19544 | BOEING 727228 | | | | OIL PRESS SWITCH 1163P005202 | FAILED NR 3 ENGINE | | 12/24/97 DHL97720001 |
| ENGINE NR 3 OIL PRESSURE LIGHT FLICKERED CLIMBING THROUGH 8,000 ON T/O. ACCOMPLISHED ALT PROC AND DETERMINED AN IMPENDING OIL BYPASS. RETURNED TO DEN. WHEN THRUST RETARDED, OIL LIGHT WENT OUT. INSPECTED AND REPLACED OIL FILTER DUE TO CARBON, LIGHT FLICKERED AGAIN DURING GROUND RUN. REPLACED OIL PRESSURE SWITCH. | | | | | | | | | |
| 2560 W8PA | 945WP 24212 | BOEING 7373K9 | | | | BRACKET | CORRODED BS 312/344 | | 9/6/97 W8PA971564 |
| PAE- CORROSION ON GIRT BAR, ATTACH POINTS, BS 312 AND 344, LBL 57, WL 208. CORROSION REMOVED, OUT OF LIMITS, REPLACE GIRT BAR ATTACH POINTS. | | | | | | | | | |
| 3350 TSAA | 821AL 23155 | BOEING 737230C | | | | BATTERY PACK 86210066 | DISCHARGED CABIN | | 11/14/97 TSAA9733292 |
| ON DAILY CHECK, FOUND POSITION NR 6 FLOOR EMERGENCY LIGHT INOP. REPLACED LIGHT BATTERY PACK. OPS CHECK OK. AIRCRAFT RETURNED TO SERVICE. (M) | | | | | | | | | |
| 3350 W8PA | 951WP 22951 | BOEING 7373B7 | | | | BULB OL3071BPEGPL | FAILED L1 DOOR | | 12/21/97 W8PA971549 |
| DEN- THRESHOLD LIGHT AT L1 DOOR IS INOP. REPLACED BULB, OPS CHECK GOOD. | | | | | | | | | |
| 3350 W8PA | 947WP 23376 | BOEING 7373B7 | | | | BULB OL3071BPEGPL | FAILED L2 DOOR | | 12/23/97 W8PA971551 |
| DEN- AFT LEFT EMERGENCY EXIT LIGHT IS INOP. REPLACED BULBS, OPS CHECK GOOD. | | | | | | | | | |
| 3350 W8PA | 952WP 23378 | BOEING 7373B7 | | | | BULB OL3071BPEGPL | FAILED L1 DOOR | | 12/21/97 W8PA971550 |
| DEN- THRESHOLD LIGHT AT L1 DOOR IS INOP. REPLACED BULB, OPS CHECK GOOD. | | | | | | | | | |
| 3350 USAA | 508AU 23383 | BOEING 7373B7 | | | | WIRE | BROKEN CABIN | | 11/3/97 USAASB97323 |
| ORD - DURING OVERNIGHT CHECK, MAINTENANCE FOUND THE MAIN ENTRY DOOR EVACUATION SLIDE LIGHT INOP AND A FORWARD SECTION OF LOW LEVEL EMERGENCY LIGHTING INOP. MAINTENANCE RELAMPED THE EVACUATION SLIDE LIGHT (P/N 1619) AND REPAIRED BROKEN WIRE/SECURED LOOSE TRACK FOR LOW LEVEL EMERGENCY LIGHTS. OPERATIONAL CHECK GOOD. (M) | | | | | | | | | |
| 3350 W8PA | 960WP 23331 | BOEING 7373L9 | | | | WIRE | DISCONNECTED CABIN | | 12/24/97 W8PA971552 |
| DEN- EMERGENCY FLOOR TRACK LIGHTING AT OVERWING EXIT IS INOP. RECONNECTED WIRE AT FORWARD LIGHT ASSY, OPS CHECK GOOD. | | | | | | | | | |
| 3350 W8PA | 956WP 24299 | BOEING 7373Q8 | | | | PIN | FAILED CABIN | | 12/25/97 W8PA971553 |
| EMERGENCY FLOOR TRACK LIGHTING AT ROW 21 IS INOP. REPLACED SOCKET PIN IN THE LIGHT AT ROW 21, OPS CHECK GOOD. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 312 | 9/6/97 | W8PA971571 |
| PAE- CORROSION ON FLOORBEAM BS 312, LBL 27, RBL 12, WL 208. REMOVED FLOORBEAM UPPER CHORD, OUT OF LIMITS, CUT OUT DAMAGE, FABRICATED AND INSTALLED PARTS. | | | | | | | | | |
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 294.5 | 9/6/97 | W8PA971565 |
| PAE- CORROSION AROUND NUT PLATE HOLES ON FLOORBEAM, UPPER CHORD, BS 294.5, WL 208, RBL 7.5, 20, 31.5, 32, 38.5 AND 44. REMOVED CORROSION, OUT OF LIMITS, CUT OF DAMAGE, FAB AND INSTALLED REPAIR PARTS. | | | | | | | | | |
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 344 | 9/6/97 | W8PA971556 |
| PAE- CORROSION ON FLOORBEAM AT BS 344, LBL 36, LBL 1, WL 208. REMOVED CORROSION, OUT OF LIMITS, REPAIRED BEAM. | | | | | | | | | |
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 328 | 9/6/97 | W8PA971572 |
| PAE- CORROSION ON FLOORBEAM BS 328, RBL 14 TO 51, WL 208. CORROSION REMOVED, OUT OF LIMITS, REPLACED UPPER CHORD 328 FLOORBEAM. | | | | | | | | | |
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 986-5 | 9/6/97 | W8PA971560 |
| PAE- CORROSION ON FLOORBEAM BS 986.5, LBL 45, RBL 37 WL 208. REMOVED ALL CORROSION, OUT OF LIMITS, CUT OF UPPER CHORD, FABRICATED NEW CHORD AND SPLICE ANGLES AND INSTALLED. | | | | | | | | | |
| 5315 W8PA | 945WP 24212 | BOEING 7373K9 | | | | FLOORBEAM | CORRODED BS 967 | 9/6/97 | W8PA971533 |
| PAE - CORROSION ON FLOORBEAM BS 967, LBL 42 - RBL 42. REMOVED ALL CORROSION, FOUND TO BE OUT OF LIMITS. REPAIRED FLOORBEAM. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 992 | 9/6/97 | W8PA971562 |
| PAE- CORROSION ON FLOOR T-SUPPORT BS 992, LBL 23 TO 37, WL 208. REMOVED CORROSION, OUT OF LIMITS, REMOVED OLD SUPPORT AND INSTALLED NEW ONE. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | MOPSILL | CORRODED BS 947-993 | 9/6/97 | W8PA971563 |
| PAE- CORROSION ON MOPSILL BS 947 TO 993, LBL 48 TO 53 WL 208 TO 209. REMOVED CORROSION, OUT OF LIMITS, REMOVED AND REPLACED MOPSILL. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CREASE BEAM | CORRODED BS 620-639 | 9/5/97 | W8PA971535 |
| PAE - CORROSION ON CREASE BEAM WEB BS 620-639, LBL 65-70, WL 208. REMOVED CORROSION, OUT OF LIMITS, REPLACED WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 951 | 9/6/97 | W8PA971566 |
| PAE- CORROSION ON FLOOR SUPPORT BS 951 RBL 45 TO 53. REMOVED CORRODED SECTION, FABRICATED AND INSTALLED REPLACEMENT PARTS. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 956 | 9/6/97 | W8PA971567 |
| PAE- CORROSION ON FLOOR SUPPORT BS 956, RBL19 TO 23, WL 208. REMOVED CORROSION, OUT OF LIMITS, REMOVED AND REPLACED FLOOR SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 952 | 9/6/97 | W8PA971568 |
| PAE- CORROSION ON FLOOR SUPPORT BS 952 RBL 8, WL 208. REMOVED CORROSION, OUT OF LIMITS, REPLACED FLOOR SUPPORT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 949 | 9/6/97 | W8PA971570 |
| PAE- CORROSION ON FLOOR SUPPORT BS 949, BL 17 TO 23, WL 208. REMOVED CORRODED SECTION, FABRICATED, REMOVED AND INSTALLED PARTS. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | ANGLE | CORRODED BS 1027.5 | 9/8/97 | W8PA971573 |
| PAE- CORROSION ON WEB SUPPORT ANGLE UNDERSIDE OF TOP HORIZONTAL SECTION AT NUT PLATE HOLE BS 1027.5, LBL 6.5, WL 208. REMOVED AND REPLACED WEB SUPPORT ANGLE. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CREASE BEAM | CORRODED BS 727 | 9/5/97 | W8PA971538 |
| PAE - CORROSION ON CREASE BEAM WEB BS 727B+11, LBL 70, WL 208. REMOVED CORROSION OUT OF LIMITS, REPLACED WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | WEB | CORRODED BS 967-986 | 9/8/97 | W8PA971575 |
| PAE- CORROSION ON WEB BS 967 TO 986, LBL 51, WL 208. REMOVED, FABRICATED AND INSTALLED WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | STIFFNER | CORRODED BS 682 | 9/5/97 | W8PA971534 |
| PAE - CORROSION ON CREASE BEAM WEB STIFFENER BS 682, RBL 69, WL 209. REMOVED AND FABRICATED THE CREASE BEAM WEB STIFFENER AND INSTALLED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 328-344 | 9/9/97 | W8PA971577 |
| PAE- CORROSION ON FLOOR SUPPORT BS 328 TO 344, LBL 10, WL 208. CORROSION REMOVED, OUT OF LIMITS, REPLACED FLOOR SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | INTERCOSTAL | CORRODED BS 344-360 | 9/9/97 | W8PA971578 |
| PAE- CORROSION ON INTERCOSTAL BS 344 TO 360, RBL 10, WL 208. CORRISION REMOVED, OUT OF LIMITS, REPLACED INTERCOSTAL. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | INTERCOSTAL | CORRODED BS 328-344 | 9/9/97 | W8PA971579 |
| PAE- CORROSION ON INTERCOSTAL, BS 328 TO 344, RBL 10, WL 208. CORROSION OUT OF LIMITS, REMOVED AND REPLACED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 301.5 | 9/22/97 | W8PA971580 |
| PAE- FLOOR SUPPORT BENEATH FWD LAVATORY ANCHOR POINT CORRODED, BS 301.5, WL 208, LBL 13. REMOVED AND REPLACED FLOOR SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 947-967 | 9/6/97 | W8PA971569 |
| PAE- CORROSION ON FLOOR SUPPORT BS 947 TO 967, RBL 18, WL 208. REMOVED CORROSION, OUT OF LIMITS, REPLACED OLD WEB WITH NEW WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | WEB | CORRODED BS 948-950 | 9/8/97 | W8PA971576 |
| PAE- CORROSION ON WEB BS 948 TO 950, LBL 55, WL 208. REMOVED CORRODED SECTION, FABRICATED AND INSTALLED REPLACEMENT PARTS. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 847-867 | 9/4/97 | W8PA971542 |
| PAE - CORROSION ON SUPPORT FOUND AT BS 847 TO 867, WL 156, RBL 23. CORROSION ON SUPPORT FOUND TO BE OUT OF LIMITS, REPLACED SUPPORT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|----------------------------|-----------|----------------------------|
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | ANGLE | CORRODED BS 248 | 9/7/97 | W8PA971547 |
| PAE- CORROSION L-ANGLE HORIZONTAL BS 248, RBL 45, WL 256. REMOVED AND REPLACED L-ANGLE CORROSION, FOUND TO BE OUT OF LIMITS. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CRACKED BS 420-440 | 9/4/97 | W8PA971548 |
| PAE- CRACKED FLOOR TO SIDEWALL SUPPORT BS 420 TO 440 RBL 25.5, WL 156.5. FLOOR SUPPORT REPLACED WITH NEW SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | WEB | MISSING BS 789/794 | 9/3/97 | W8PA971539 |
| PAE - WEB AT BS 789, BS 794, RBL 24-RBL 31 HAS PIECE MISSING. REMOVED WEB FABRICATED AND INSTALLED NEW WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 787/807 | 9/21/97 | W8PA971541 |
| PAE - CORROSION ON FLOOR TO SIDEWALL SUPPORT UNDER NUTPLATES AT BS 787 TO BS 807, WL 156, RBL 21. CORROSION REMOVED, OUT OF LIMITS, REPLACED FLOOR TO SIDEWALL SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | WEB | CORRODED BS 789 | 9/3/97 | W8PA971540 |
| PAE - CORROSION AROUND NUTPLATE HOLES AT BS 789, RBL 24-RBL 60. REMOVED CORROSION, THEN DISCOVERED WEB TO BE CRACKED, FABRICATED AND INSTALLED NEW WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 846-500 | 9/4/97 | W8PA971544 |
| PAE - CORROSION UNDER NUTPLATES ON FLOOR TO SIDEWALL SUPPORT BS 846 TO BS 500D, LBL 26, WL 156. REMOVED CORROSION, OUT OF LIMITS, FABRICATED AND INSTALLED NEW SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | WEB | CORRODED BS 986.5-1016 | 9/6/97 | W8PA971561 |
| PAE- CORROSION ON WEB BS 96.5 TO 1016, LBL 36 TO 46, WL 208. FOUND WEB TO BE BLENDED OUT OF LIMITS, INSTALLED NEW WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | INTERCOSTAL | CORRODED BS 967.5-987.5 | 9/6/97 | W8PA971581 |
| PAE- INTERCOSTAL CORRODED AT STRINGER 21 BETWEEN FRAME BS 967.5 TO 987.5, RIGHT BUTT LINE 40. BLENDED CORROSION, OUT OF LIMITS, REMOVED, FABRICATED AND INSTALLED NEW INTERCOSTAL. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | STRAP | CORRODED BS 1006-1030 | 9/6/97 | W8PA971559 |
| PAE- CORROSION ON WEB STRAP BS 1006 TO 1030, LBL 3 TO 8, WL 208. CORROSION REMOVED, OUT OF LIMITS, REPLACED WITH NEW STRAP. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 947 | 9/6/97 | W8PA971532 |
| PAE - CORROSION ON FLOOR SUPPORT AT BS 947-967, RBL 41, WL 208. REMOVED CORROSION FOUND TO BE OUT OF LIMITS. REMOVED AND REPLACED FLOOR SUPPORT. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 500 | 9/4/97 | W8PA971546 |
| PAE- CORROSION UNDER NUT PLATE LT SIDEWALL TO BULKHEAD SUPPORT BS 500D, WL 158, LBL 35 TO 25. REMOVED CORROSION, OUT OF LIMITS, REMOVED OLD SUPPORT AND INSTALLED NEW SUPPORT. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CREASE BEAM | CORRODED BS 697 | 9/5/97 | W8PA971536 |
| PAE - CORROSION ON CREASE BEAM WEB BS 697, RBL 68, WL 208. REMOVED CORROSION ON CREASE BEAM WEB BS 697, RBL 68, WL 208, WAS WITHIN LIMITS. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | BEAM | DAMAGED BS 727 | 9/5/97 | W8PA971554 |
| PAE- TWO DOUBLE HOLES ON LONGITUDINAL BEAM, ONE AT BS 727A + 8, ONE AT BS 727A+14, RBL 1, WL 208. CUT OUT DAMAGED SECTION OF BEAM, FABRICATED REPAIR PARTS AND INSTALLED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 956 | 9/6/97 | W8PA971555 |
| PAE- CORROSION ON FLOOR SUPPORT AROUND FASTENERS HOLES BS 956, RBL 27 TO 40, WL 208. FABRICATED NEW FLOOR SUPPORT AND INSTALLED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | ANGLE | CRACKED BS 291-296 | 9/26/97 | W8PA971557 |
| PAE- CRACKED RADIUS ON AFT END OF ATTACH ANGLE, BS 291.5 TO 296, RBL 54, WL 208. REMOVED AND REPAIRED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CHANNEL | CORRODED BS 298-340 | 9/6/97 | W8PA971558 |
| PAE- CORROSION OF C-CHANNEL AT BS 298 TO 340, WL 209, RBL 60. REMOVED AND REPLACED C-CHANNEL. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | SUPPORT | CORRODED BS 500 | 9/4/97 | W8PA971543 |
| PAE-CORROSION UNDER NUTPLATES ALONG FLOOR TO SIDEWALL SUPPORT, BS 500 TO BS 500D, WL 156, RBL 26. REMOVED ALL CORROSION, WITHIN ALLOWABLE LIMITS, ALODINED AND PAINTED. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CREASE BEAM | CORRODED BS 616-639 | 9/5/97 | W8PA971537 |
| PAE - CORROSION ON CREASE BEAM WEB BS 616-639, RBL 70, WL 208. REMOVED CORROSION OUT OF LIMITS, REMOVED AND INSTALLED NEW WEB. | | | | | | | | | |
| 5320 W8PA | 945WP 24212 | BOEING 7373K9 | | | | INTERCOSTAL | CORRODED BS 1019.5 | 9/8/97 | W8PA971574 |
| PAE- CORROSION ON UNDERSIDE OF TOP HORIZONTAL SECTION OF INTERCOSTAL AROUND NUT PLATE, HOLE AT BS 1019.5, LBL 27.5, WL 208. FABRICATED INTERCOSTAL AND INSTALLED. | | | | | | | | | |
| 5347 W8PA | 945WP 24212 | BOEING 7373K9 | | | | CARGO TRACK | CORRODED BS 500 | 9/4/97 | W8PA971545 |
| PAE - CORROSION UNDER NUTPLATES ON CARGO TRACK, BS 500C+15 WL 156, LBL 18. REMOVED AND REPLACED DAMAGED SECTION FORM BS 500B+10 TO 500D. | | | | | | | | | |
| 2131 IPXA | 681UP 19661 | BOEING 747121 | | | | CONTROLLER 7102977 | MALFUNCTIONED CABIN | 12/23/97 | UPS97425355 |
| INSPECTION TYPE-N/A, DURING CABIN CLIMBOUT AT 18,000 CABIN PRESS BEGAN CLIMBING ABOVE 9,000 FT THE CABIN ALT WAS SET AT 6,000. THE AUTO FAIL LIGHT ILLUM AND PRESS DIFF WAS 8.4 APPROX 2 MIN LATER CABIN CLIMBED ABOVE 10,000 AND PRESS RELIEF VALVES WERE CLOSED AND THE UPPER PRESS RELIEF VALVE LIGHT REMAINED ON. DESCENDED BELOW 10,000 FT W/OUTFLOW VALVES OP. REPLACED AUTO PRESSURE CONTROLLER BITE CHECK OK. | | | | | | | | | |
| 3350 IPXA | 672UP 20324 | BOEING 747123F | | | | CONNECTOR | FAILED FLIGHT DECK | 12/6/97 | UPS97425332 |
| INSPECTION TYPE-N/A, FLIGHT DECK EMERGENCY EXIT CEILING LIGHT INOP. FOUND BAD CONTACT, ADJUSTED AS REQUIRED, F/C OK. THIS CLOSSES M-143122 (REF LOG PAGE 991265). | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|--------------------------------|-----------|----------------------------|
| 3350 NWAA | 661US 23719 | BOEING 747451 | | | | CONNECTOR | LOOSE CABIN | | 12/24/97 9724336301 |
| DURING LINE CHECK, FOUND ESCAPE PATH EMERGENCY LIGHTS INOPERATIVE AT DOOR 3L AND FROM ROWS 35HJK TO 43HJK. RECONNECTED LIGHT ASSEMBLIES, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 NWAA | 663US 23818 | BOEING 747451 | | | | WIRING | LOOSE CABIN | | 12/24/97 9724346303 |
| DURING LINE CHECK, FOUND FLOOR PATH EMERGENCY LIGHTS INOPERATIVE FROM ROWS 24 TO 32. RECONNECTED WIRING, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 NWAA | 670US 24225 | BOEING 747451 | | | | WIRING | FAILED CABIN | | 12/25/97 9724326310 |
| DURING LINE CHECK, FOUND LEFT SIDE D-ZONE FLOOR PATH EMERGENCY LIGHTS INOPERATIVE. REPAIRED WIRING, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 DALA | 615DL 22822 | BOEING 757232 | | | BPS73 | POWER SUPPLY | INOPERATIVE R2 DOOR | | 12/24/97 DL757972715 |
| R2 DOOR EXIT SIGN INOP. REPLACED POWER SUPPLY. | | | | | | | | | |
| 5210 DALA | 667DN 25035 | BOEING 757232 | | | 80330035 | ASSIST BOTTLE | LOW PRESSURE L1 DOOR | | 12/24/97 DL757972730 |
| L1 DOOR POWER ASSIST BOTTLE PRESS LOW. REPLACED BOTTLE. | | | | | | | | | |
| 5610 IPXA | 431UP 25462 | BOEING 75724APF | | | | WINDOW | LACK OF LUBE LT COCKPIT | | 12/23/97 UPS97525356 |
| INSPECTION TYPE-N/A, CAPT WINDOW DIFFICULT TO UNLATCH. REMOVED DEBRIS FROM LOWER LATCH AND LUBRICATED, WINDOW LATCH OPS CHECKS GOOD PER MM 56-11-02 P519. | | | | | | | | | |
| 5610 IPXA | 431UP 25462 | BOEING 75724APF | | | | WINDOW | LACK OF LUBE LT COCKPIT | | 12/23/97 UPS97525357 |
| INSPECTION TYPE-N/A, CAPT WINDOW DIFFICULT TO UNLATCH. ADJUSTED WINDOW IAW M/M 56-11-02 AND FOUND INSPECTORS PUTTY ON ALL 4 PIN THAT WAS IN A SOLID STATE. CLEANED APPLIED LUBE WINDOW CK'D OK. | | | | | | | | | |
| 5610 IPXA | 431UP 25462 | BOEING 75724APF | | | | WINDOW | LACK OF LUBE RT COCKPIT | | 12/23/97 UPS97525358 |
| INSPECTION TYPE-N/A, F/O WINDOW DIFFICULT TO UNLATCH. ADJUSTED WINDOW IAW M/M 56-11-01. FOUND INSPECTION PUTTY ON ALL 4 LATCH CAMS IN A SOLID STATE. CLEANED AND RE-LUBED LATCH CAMS, WINDOW OPS CKS OK. | | | | | | | | | |
| 5754 DALA | 615DL 22822 | BOEING 757232 | | | | WEDGE 114N4004157 | DELAMINATED NR 3 LE SLAT TE | | 12/17/97 DL757972695 |
| THE NR 3 SLAT WAS FOUND WITH A 4 BY 2 AREA OF DELAMINATION ON THE TRAILING EDGE WEDGE. A COMPOSITE REPAIR WAS INSTALLED PER THE B757 SRM AND DOCUMENTED PER ER/A 363470-14AD. | | | | | | | | | |
| 2910 DALA | 112DL 22224 | BOEING 767232 | GE CF680A2 | | | BRACKET | BROKEN NR 2 ENGINE | | 12/18/97 DL767972679 |
| DURING MTC, AFTER OPERATING THE RT ENG TO IDLE FOR HIGH OIL CONSUMPTION CHECKOUT, FOUND FUEL RUNNING FROM RT ENG STRUT DRAINLINE. INSPECTED AREA, FOUND ENG FUEL FEED LINE COUPLING AT THE TOP OF THE STRUT JUST FWD OF THE WING LE CHAFFED THRU DUE TO A BROKEN HYD LINE BRACKET. REPLACED COUPLING AND PACKINGS. FWD BROKEN BRACKET TO MCO O18770009. NEEDS (P/N 312T1079-227) OR TO BE MADE OUT OF .063 STAINLESS STEEL. | | | | | | | | | |
| 5330 DALA | 110DL 22222 | BOEING 767232 | | | | SKIN | PUNCTURED BS 422 | | 12/18/97 DL767972696 |
| THE FUSELAGE SKIN AT FS 422 BETWEEN STRINGERS 21L AND 22L WAS PUNCTURED BY GROUND EQUIPMENT. THE FINAL SKIN CUTOUT WAS 6.5 BY 5. THE DAMAGE WAS REPAIRED WITH A SKIN DOUBLER. INSTALLED PER THE PROCEDURES OF THE B767 SRM AND DOCUMENTED PER ER/A 300885-14, REV B. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|-------------------------------|---------------|----------------------------|
| 5330 DALA | 131DN 24852 | BOEING 767332 | | | | SKIN | PUNCTURED BS 308 | | 12/23/97 DL76S972720 |
| THE FUSELAGE SKIN WAS PUNCTURED AND TRIMMED AWAY OVER AN 8 BY 8 AREA BETWEEN FS 303 AND 311 AND BETWEEN STRINGERS 26L AND 29L. STRINGERS 27L AND 28L WERE SEVERED AND REPAIRED PER SRM. THE SKIN WAS REPAIRED WITH AN EXTERNAL ALUMINUM DOUBLER PER ER/A 363527-14, REV A. | | | | | | | | | |
| 2750 COMA | 931CA 7037 | CNDAIR CL6002B19 | | | | BPSU 855D1007 | FAILED RT TE FLAP | 4704 424 | 12/27/97 COMA9760257 |
| FLAPS FAILED AT ZERO DEGREES. REPLACED THE RIGHT HAND FLAP BRAKE AND POSITION UNIT. | | | | | | | | | |
| 2751 COMA | 933CA 7040 | CNDAIR CL6002B19 | | | | FLAP WARNING | ACTIVATED TE FLAPS | | 12/23/97 COMA9760254 |
| FLAPS FAIL CAUTION MESSAGE WHEN FLAPS SELECTED UP AFTER TAKEOFF. COULD NOT DUPLICATE DISCREPANCY. OPERATIONAL CHECK OF FLAP SYSTEM SATISFACTORY. | | | | | | | | | |
| 2752 COMA | 949CA 7080 | CNDAIR CL6002B19 | | | | ACTUATOR 852D1009 | FAILED LT TE FLAP | | 12/27/97 COMA9760258 |
| FLAPS FAIL MESSAGE AFTER TAKEOFF WHEN FLAPS SELECTED UP. REPLACED DEFECTIVE LEFT HAND OUTBOARD FLAP ACTUATOR. | | | | | | | | | |
| 3030 COMA | 931CA 7037 | CNDAIR CL6002B19 | | | | CONTROLLER | TRIPPED PITOT HEAT | | 12/25/97 COMA9760255 |
| STANDBY PITOT HEAT CAUTION MESSAGE. RESET HEAT CONTROLLER. PROBLEM DOES NOT DUPLICATE. | | | | | | | | | |
| 3240 COMA | 958CA 7111 | CNDAIR CL6002B19 | | | | VALVE 158861 | DEFECTIVE PARKING BRAKE | 5039 | 12/27/97 COMA9760256 |
| PARKING BRAKE AND ANTI-SKID CAUTION MESSAGE DURING LANDING APPROACH. REPLACED THE PARKING BRAKE SHUT OFF VALVE. | | | | | | | | | |
| 3620 COMA | 981CA 7163 | CNDAIR CL6002B19 | | | | CONTROL UNIT 20035008067 | MALFUNCTIONED RT BLEED AIR | 4819 | 12/24/97 COMA9760260 |
| RIGHT HAND 14TH STAGE BLEED AIR DUCT WARNING. COULD NOT DUPLICATE DISCREPANCY. REPLACED BLEED LEAK CONTROL UNIT FOR TROUBLESHOOTING. | | | | | | | | | |
| 3620 COMA | 984CA 7171 | CNDAIR CL6002B19 | | | | WARNING | ACTIVATED RT BLEED AIR | | 12/24/97 COMA9760259 |
| LEFT HAND AND RIGHT HAND BLEED AIR DUCT LEAK WARNING MESSAGE. COULD NOT DUPLICATE DISCREPANCY. SYSTEM TEST WAS NORMAL. | | | | | | | | | |
| 7200 COMA ***** | 959CA 7116 | CNDAIR CL6002B19 | GE CF343A1 | | | ENGINE | FAILED RIGHT | | 12/22/97 COMA9760253 |
| UNCOMMANDED ACCELERATION OF RIGHT ENGINE ALL ENGINE PARAMETERS WERE EXCEEDED. REPLACED ENGINE. | | | | | | | | | |
| 6110 | | DHAV DHC7* | | HAMSTD 24PF305 | | SHEATH PFA12D19B | CRACKED PROP ASSY | 18628 4803 | 10/1/96 EY2R9600129 |
| PROP ASSY HAS 3 SHEATHS CRACKED | | | | | | | | | |
| 2611 QXEA | 841PH 82 | DHAV DHC8102 | | | KIDDE 82522710001 | LAMP MS2523787 | FAILED NR 2 SMOKE DET | | 12/23/97 QXEA9700916 |
| SEA- BAGGAGE SMOKE WARNING TEST NR 2 INOP. TEST NR 1 WORKS NORMAL. RELAMPED TEST CIRCUIT OF NR 2 SMOKE DETECTOR, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 2612 QXEA | 840PH 74 | DHAV DHC8102 | | | | BULB MS25237327 | FAILED NR 1 T-HANDLE | | 12/28/97 QXEA9700925 |
| SEA - NR 1 FIRE T-HANDLE DETECTION LAMP BURNED OUT. RELAMPED AS REQUIRED, OPERATIONAL CHECK GOOD. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|---|-------------------------|---------------------|-----------------------|-------------------------|----------------------------|----------------------------|-----------|----------------------------|
| 5210 QXEA | 816PH 54 | DHAV DHC8102 | | | | CABLE 85210368101 | INOPERATIVE CABIN DOOR | | 12/24/97 QXEA9700919 |
| PDX- MAIN CABIN DOOR WON'T OPEN. REPLACED CABLE AND ASSIST STRUTS, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 5210 QXEA | 840PH 74 | DHAV DHC8102 | | | DHAV 85210152001 | SUPPORT ROD 85210241103 | BROKEN CABIN DOOR | | 12/24/97 QXEA9700924 |
| SEA- MAIN CABIN DOOR WILL NOT OPEN. EXITED THROUGH EMERGENCY DOOR. REPLACED BROKEN SUPPORT ROD, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 5210 QXEA | 840PH 74 | DHAV DHC8102 | | | | MECHANISM | OUT OF ADJUST PAX DOOR | | 12/24/97 QXEA9700918 |
| YVR- MAIN CABIN DOOR WILL NOT OPEN. EXITED THROUGH EMERGENCY EXIT. CABIN DOOR UNJAMMED, ALL DOOR STOPS, FITTINGS INSPECTED WITH NO DEFECTS NOTED. DOOR LINKAGE IN WARDROBE INSPECTED WITH NO DEFECTS NOTED. CABIN DOOR LUBRICATED AND FUNCTION CHECKED SERVICEABLE. AIRSTAIR DOOR ROD AND HANDLES INSPECTED NOTING UPPER DOOR SUPPORT ROD SWAGED END LOOSE. SERVICEABLE FOR FURTHER FLIGHT, TO BE REPLACED AT NEXT MAINTENANCE BASE. | | | | | | | | | |
| 6140 QXEA | 355PH 500 | DHAV DHC8202 | | | | RELAY YD4N | MALFUNCTION E/E COMPT | | 12/24/97 QXEA9700920 |
| PDX- AUTO FEATHER TEST INOP. AUTO FEATHER ARMS NORMALLY. REPLACED RELAYS 6121-K3 AND 6121-K4. ACCOMPLISHED AUTO FEATHER SYSTEM AND POWER UPTRIM TEST, SYSTEM TESTS GOOD. | | | | | | | | | |
| 5270 M8XA | 332PH 3010 | DORNER DO328100 | PWA PW119C | HARTZL HDE6C3B | DORNIER 001A521B0145 | BRACKET | FAILED PAX DOOR | | 12/26/97 M8XA9700022 |
| EN ROUTE, THE CREW RECEIVED A DOOR WARNING INDICATION. ACFT RETURNED, LANDED WITHOUT FURTHER INCIDENT. MX DISCOVERED THE PAX DOOR PROXIMITY SENSOR TARGET WAS MISRIGGED. ALSO, THE PROXIMITY SENSOR BRACKET WAS DAMAGED SEVERAL ATTACH RIVETS WERE LOOSE. ACFT WAS THEN FLOWN TO COS, WHERE MX REPLACED THE DOOR HANDLE BELLCRANK ASSEMBLY COMPLETE WITH NEW PROX TARGET BRACKET. ALL WORK ACCOMPLISHED IAW AMM 52-71-00. ALL GROUND OPERATIONAL CHECKS WERE SATISFACTORY. ACFT WAS RELEASED FOR SERVICE. THIS IS THE SECOND OCCURANCE OF THIS DISCREPANCY IN THE LAST THREE DAYS. | | | | | | | | | |
| 6120 VNAA | 433JS 3047 | DORNER DO328100 | PWA PW119B | HARTZL HDE6C3B | | CIRCUIT BREAKER | TRIPPED PROP OVERSPEED | | 12/21/97 VNAA9712015 |
| DURING TAXI, THE CREW ATTEMPTED A PROP OVERSPEED TEST. THE TEST FAILED, AND THE AIRCRAFT RETURNED TO THE GATE. PIT MAINTENANCE INSPECTED AND RESET THE OVERSPEED CIRCUIT BREAKER. OPERATION CHECKS WERE COMPLIED WITH IN ACCORDANCE WITH DORNIER MAINTENANCE MANUAL 71-01-00, AND THE AIRCRAFT WAS RETURNED TO SERVICE. | | | | | | | | | |
| 6110 | | DOUG B18A | | HARTZL HCB3R302 | | CLAMP 1977 | CORRODED PROPELLER ASSY | | 9/1/96 EY2R9601000 |
| CORROSION FOUND ON CLAMP. | | | | | | | | | |
| 7230 NWAA | 160US 46769 | DOUG DC1040 | PWA JT9D20J | | | COMPRESSOR | STALLED NR 3 ENGINE | | 12/22/97 9724251160 |
| ***** | DURING LANDING ROLLOUT, WHILE IN REVERSE THRUST THE NR 3 ENGINE COMPRESSOR STALLED. THE EGT ROSE TO 880C BEFORE THE ENGINE WAS SHUT DOWN. MAINTENANCE INSPECTED THE ENGINE PER MM71-00-00 WITH NO DEFECTS NOTED. THE ENGINE WAS RUN WITH NORMAL INDICATIONS. THE NR 3 THRUST REVERSER WAS PLACED ON MEL AND THE AIRCRAFT RETURNED TO SERVICE. | | | | | | | | |
| 2120 TC8A | 182SK 45817 | DOUG DC8F55 | | | | AIR DISTR | SMOKE COCKPIT | | 12/29/97 TC8A97056 |
| SMOKE INSIDE THE AIRCRAFT, RETURNED TO MIA. CHECKED ALL FOUR ENGINE, OIL LEAK OK. RAN ENGINE ONE AT A TIME WITH BLEEDS ON AND NASI SYSTEM OPERATING, LT AND RT NO SMOKE ENTERING COCKPIT. RAN ALL FOUR ENGINES WITH ALL FOUR BLEEDS ON AND NASI SYSTEM OPERATING, COULD NOT GET SMOKE INTO COCKPIT ON GROUND. OPS CHECKS NORMAL IAW MAINTENANCE MANUAL 21-2-0 AND M/M 36-00. | | | | | | | | | |

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------------|----------------------------|---------------|----------------------------|
| 2121 IXXA | 41CX 46129 | DOUG DC862F | | | | FAN X207256D | FAILED COCKPIT | | 12/19/97 IXXA9700169 |
| EN ROUTE, A BURNT ODOR WAS SENSED IN THE COCKPIT WITH THE LEFT RECIRCULATION FAN OPERATING. THE FAN WAS SHUT OFF FOR THE REMAINDER OF THE FLIGHT. MAINTENANCE FOUND THE FAN DEFECTIVE. MAINTENANCE DEFERRED THE LEFT RECIRCULATION FAN. | | | | | | | | | |
| 2612 RRXA | 801GP 46039 | DOUG DC871F | | | | FIRE WIRE | BROKEN NR 4 ENGINE | | 12/24/97 RRXA97326 |
| NR 4 ENGINE FIRE WARNING CAME ON MOMENTARILY DURING LANDING, WILL NOT TEST. REPAIRED BROKEN WIRE AT AFT FIRELOOP. NR 4 ENGINE FIRE WARNING OPS CHECKS GOOD. | | | | | | | | | |
| 2913 RRXA | 8079U 45947 | DOUG DC871F | | | | HYD PUMP 55107 | LEAKING NR 3 ENGINE | | 12/21/97 RRXA97325 |
| LEAK IN HYD SYSTEM (VERY SLOW AND CONTINUED WITH BOTH PUMPS BYPASSED AND HYD CONT LEVER DOWN). PERFORMED PROCEDURES IAW QRH. FOUND NR 3 ENGINE HYD PUMP LEAKING. REMOVED AND REPLACED HYD PUMP, RAN NR 3 ENG. OP CK GOOD, NO LEAKS NOTED. | | | | | | | | | |
| 3230 RRXA | 801GP 46039 | DOUG DC871F | | | | BOGGIE ACTUATOR 56165545503 | FAILED RT MLG | | 12/19/97 RRXA97324 |
| LANDING AT EWR OTHER A/C REPORTED SMOKE RT MAIN. REMOVED AND REPLACED RT BOGGIE TRIM ACT IAW DC-8 MM 32-31-18. SYSTEM LEAK CHK NORMAL. | | | | | | | | | |
| 3260 RRXA | 996CF 46162 | DOUG DC862F | | | | PROX SENSOR | DIRTY NLG | | 12/19/97 RRXA97323 |
| NOSE GEAR GREEN LIGHTS WENT OUT AT 200 FEET AURAL WARNING CAME ON, INITIATED GO AROUND, GEAR LIGHTS CAME BACK ON. ALL SYSTEM CHECKED NORMAL, LANDED. INSPECTED NOSE GEAR DOWN LOCK ASSY CLEANED AND ADJUSTED DOWN AND LOCKED PROX SENSOR IAW 32-20. | | | | | | | | | |
| 5330 CKSA | 868BX 46034 | DOUG DC863 | | | | SKIN | DAMAGED FUSELAGE | | 12/6/97 CKSA97610 |
| AIRCRAFT DAMAGED BY FORKLIFT APPROX 2 FOOT FOWARD OF LEFT WING ROOT. INSPECTED AND REPAIRED DAMAGE IAW DC8 SRM 53-2-1, LOG PAGE 999-3485. | | | | | | | | | |
| 2450 VJ6A | 935VV 47534 | DOUG DC932 | | | | CIRCUIT BREAKER 5D000950 | FAILED COCKPIT | | 12/26/97 VJ970367 |
| AT CRUISE NUMEROUS CIRCUIT BREAKERS TRIPPED WITHIN SECONDS OF EACH OTHER. REMOVED AND REPLACED LEFT PHASE 0 C 50 AMP CIRCUIT BREAKER IAW MM 24-20. | | | | | | | | | |
| 2560 VJ6A | 946VV 47226 | DOUG DC932 | | | | SLIDE 591769637 | FELL OFF L 1 DOOR | | 12/25/97 VJ970366 |
| PASSENGER ENTRY DOOR EMERENCY SLIDE CAME OFF. REINSTALLED PASSENGER ENTRY DOOR EMERGENCY SLIDE IAW MM 25-62-0. | | | | | | | | | |
| 2560 VJ6A | 924VV 47278 | DOUG DC932 | | | | SLIDE 591769637 | FELL OFF PAX DOOR | | 12/29/97 VJ970368 |
| PASSENGER ENTRY DOOR EMERENCY SLIDE CAME OFF. REINSTALLED PASSENGER ENTRY DOOR EMERENCY SLIDE IAW MM 25-62-0. | | | | | | | | | |
| 2560 VJ6A | 930VV 47723 | DOUG DC932 | | | | COVER 113317 | FELL OFF R1 DOOR | | 12/24/97 VJ970365 |
| FORWARD GALLEY DOOR EMERGENCY SLIDE COVER CAME OFF. REINSTALLED FORWARD GALLEY DOOR EMERGENCY SLIDE COVER IAW MM 25-61. | | | | | | | | | |
| 2565 NWAA | 940N 47572 | DOUG DC932 | | | | SLIDE 113317 | LOW PRESSURE CABIN DOOR | 34409 3899 | 12/23/97 9724249918 |
| DURING LINE MAINTENANCE INSPECTION, FOUND RIGHT FORWRD CABIN DOOR EVACUATION SLIDE LOW ON PRESSURE. REPLACED SLIDE. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|----------------------------|-----------|----------------------------|
| 3010 NWAA | 621NW 47544 | DOUG DC932 | | | | CONTROL UNIT | FAILED LEFT | | 12/25/97 9724269621 |
| DURING CLIMBOUT, THE LEFT ICE PROTECTION TEMPERATURE HIGH LIGHT ILLUMINATED ONCE THE ANTI-ICE SWITCH WAS TURNED TO THE OFF POSITION. FLIGHT CREW CONSULTED WITH MAINTENEANCE CONTROL, RETURNED TO ORIGINATION AND LANDED WITHOUT INCIDENT. MAINTENANCE REPLACED THE THERMO-ELECTRIC CONTROL UNIT, THE LEFT HIGH TEMPERATURE SENSOR, AND THE LEFT ANTICIPATOR AND THERMOSTAT, OPERATIONAL CHECK OK. | | | | | | | | | |
| 3320 CALA | 69523 47520 | DOUG DC932 | | | | TRANSFORMER | FAILED CABIN | | 12/23/97 CALA9701796 |
| SPARKS AND SMOKE CAME FROM A LEFT OVERHEAD BIN WHEN BIN WAS OPENED BY A PASSENGER WHILE AIRCRAFT WAS AT GATE IN ELP. THE CIRCUIT BREAKER POPPED AND THE SMOKE AND SPARKS CEASED. MAINTENANCE FOUND TRANSFORMER IN OVERHEAD BIN AT FAULT. THE AIRCRAFT WILL BE FERRIED TO HOUSTON FOR TRANSFORMER REPLACEMENT, INSPECTION, AND REPAIRS. | | | | | | | | | |
| 3350 NWAA | 603NW 47101 | DOUG DC932 | | | | CONNECTOR | LOOSE CABIN | | 12/24/97 9724279603 |
| DURING LINE CHECK, FOUND SEAT 13 EMERGENCY PATHWAY LIGHT INOPERATIVE. MAINTENANCE RESEATED CONNECTOR UNDER SEAT LEG, OPERATIONAL CHECK OK. | | | | | | | | | |
| 3350 NWAA | 9846 47383 | DOUG DC932 | | | | POWER SUPPLY | INOPERATIVE LT NACELLE | | 12/23/97 9724239984 |
| DURING LINE MAINTENANCE INSPECTION, FOUND LEFT ENGINE NACELLE EMERGENCY LIGHT INOPERATIVE. REPLACED BATTERY POWER SUPPLY, OPERATIONAL CHECK NORMAL. | | | | | | | | | |
| 3350 NWAA | 610NW 47432 | DOUG DC932 | | | | BATTERY PACK | DISCHARGED CABIN | | 12/23/97 9724219610 |
| FLIGHT ATTENDANT REPORTED AFT EMERGENCY FLASHLIGHT INOPERATIVE. REPLACED BATTERY PACK, OPERATIONAL CHECK NORMAL. | | | | | | | | | |
| 3350 NWAA | 752NW 47116 | DOUG DC941 | | | | BATTERY | DISCHARGED CABIN | | 12/28/97 9724299752 |
| DURING LINE CHECK, FOUND FORWARD RIGHT HAND AND LEFT HAND EMERGENCY EXIT LIGHTS INOPERATIVE. MAINTENANCE REPLACED BATTERY PACK, OPERATIONAL CHECK NORMAL. | | | | | | | | | |
| 3350 NWAA | 759NW 47287 | DOUG DC941 | | | | LIGHT | INOPERATIVE CABIN | | 12/26/97 9724319759 |
| DURING LINE CHECK, FOUND EMERGENCY EXIT LIGHT AT SEAT ROW 3 INOPERATIVE. MAINTENANCE INSTALLED NEW EMERGENCY EXIT LIGHT AT SEAT ROW 3, OPERATIONAL CHECK OK. | | | | | | | | | |
| 3350 NWAA | 787NC 48149 | DOUG DC951 | | | | POWER SUPPLY | INOPERATIVE CABIN | | 12/27/97 9724289878 |
| PILOT REPORTED EMERGENCY LIGHTS AT SEAT ROWS 5 THROUGH 8 ILLUMINATED DURING FLIGHT AND WILL NOT TEST PROPERLY. MAINTENANCE REPLACED POWER SUPPLY AND BATTERY PACK AT STATION 711, OPERATIONAL CHECK OK. | | | | | | | | | |
| 3350 NWAA | 301RC 48054 | DOUG DC982 | | | | BATTERY | DISCHARGED CABIN | | 12/27/97 9724309301 |
| DURING LINE CHECK, FOUND TAIL COMPARTMENT EMERGENCY EXIT LIGHTS INOPERATIVE. MAINTENANCE REPLACED BATTERIES, OPERATIONAL CHECK OK. | | | | | | | | | |
| 3418 NWAA | 9332 47264 | DOUG DC931 | | | | STALL WARNING | MALFUNCTIONED E/E COMPT | | 12/23/97 9724229968 |
| STALL INDICATION FAILURE LIGHT ILLUMINATED AFTER TAKEOFF. FLIGHT WAS RETURNED TO DTW AND LANDED WITHOUT INCIDENT. MAINTENANCE FOUND CROSS MONITOR PINS DOWN ON BOTH STALL WARNING COMPUTERS. RESET PINS. ALSO, REPLACED STALL WARNING TONE GENERATOR, OPERATIONAL CHECK NORMAL. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--------------|---|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|----------------------------|---------------|----------------------------|
| 7320 NWAA | 923RW 47183 | DOUG DC931 | PWA JT8D15 | | | PT2 LINE | CRACKED RT ENGINE | | 12/23/97 9724209956 |
| | RIGHT ENGINE EPR INDICATION FAILED TO REACH TARGET VALUE DURING TAKEOFF ROLL. THE TAKEOFF WAS ABORTED AND THE FLIGHT RETURNED TO THE GATE. MAINTENANCE REPLACED THE RIGHT ENGINE NOSE DOME ASSEMBLY WITH A SERVICEABLE UNIT. RUN-UP AND OPERATIONAL CHECKS WERE SATISFACTORY. | | | | | | | | |
| 2140 DALA | 965DL 49984 | DOUG MD88 | | | 1116961 | HEATER | SMOKING CARGO COMPT | | 12/26/97 DLM88972739 |
| | SMOKE IN CABIN. DIVERTED TO JAN. REPLACED FORWARD CARGO HEATER. | | | | | | | | |
| 3230 DALA | 909DL 49540 | DOUG MD88 | | | | BEARING B538DDFS464 | RUSTED NLG | | 12/23/97 DLM88972724 |
| | WHILE WORKING CORROSION VISIT ITEMS THE NLG UPPER DRAG BRACE WAS REPLACED REF NR 26. DURING AFTER REPLACEMENT CHECKOUT THE NLG ALTERNATE EXTENSION LINKAGE WAS FOUND FROZEN UP AND THE GEAR WOULD NOT EXTEND USING THIS METHOD. ON FURTHER INSPECTION THE NLG UPLOCK RELEASE MECHANISM WAS FOUND TO HAVE RUSTED AND WORN BEARINGS REF NR 124. AFTER BEARING REPLACEMENT THE SYSTEM CHECKED NORMAL PER MM REF IPC 32-30-00-01A FIG 01A SHEET 2 ITEM 605. | | | | | | | | |
| 5311 DALA | 982DL 53273 | DOUG MD88 | | | | FRAME 5913595501 | CRACKED BS 1418 | | 12/23/97 DLM88972710 |
| | FS 1418 FOUND CRACKED AT L2R. TYPICAL LOCATION FOR EARLIER AC BUT FACTORY/PRODUCTION MOD WAS TO PREVENT PROBLEM. WILL REPAIR SAME WAY AS REPAIR FOR EARLIER AC. REPAIR PER ERA 331142-14. | | | | | | | | |
| 5320 DALA | 908DL 49539 | DOUG MD88 | | | | JAMB | CORRODED C1 DOOR | | 12/20/97 DLM88972686 |
| | FWD CARGO DOOR OPENING LWR JAMB PAN HAD EXTENSIVE CORROSION. REPAIRED PER ERA 331138-14. | | | | | | | | |
| 2130 SWIA | 237SW 120314 | EMB EMB120ER | PWA PW118A | | | VALVE | FAILED CABIN | | 11/24/97 SWIA971035 |
| | AUTO AND MANUAL PRESSURIZATION INOP. RETURNED TO THE GATE IN SLC. REMOVED AND REPLACED ELECTRO/PNEUMATIC VALVE IAW MM 21-30-3. AUTO AND MANUAL PRESSURIZATION OPS CHECKS GOOD. | | | | | | | | |
| 2150 COMA | 130G 120130 | EMB EMB120RT | | | | ACM 22045402 | FAILED LEFT | 3276 1411 | 12/19/97 COMA9710500 |
| | LAV SMOKE DETECTOR ACTIVATED. CABIN FILLED WITH SMOKE. REPLACED THE LEFT AIR CYCLE MACHINE. | | | | | | | | |
| 2722 SWIA | 193SW 120088 | EMB EMB120ER | PWA PW118A | | | ACTUATOR 3081401003 | FAILED RUDDER | | 12/1/97 SWIA971037 |
| | RIGHT RUDDER TRAVEL IS RESTRICTED IN FLIGHT WITH YAW DAMPER OFF. REPLACED RUDDER A ACTUATOR IAW MM 27-20-00. OPS CHECK GOOD WITH NO LEAKS NOTED. | | | | | | | | |
| 2751 COMA | 161CA 120143 | EMB EMB120RT | | | | ANNUNCIATOR PNL 3069001017 | MALFUNCTION COCKPIT | 4292 | 12/21/97 COMA9710501 |
| | FLAP CONTROL FAULT, ASYMMETRY AND DISAGREEMENT WARNINGS. REPLACED THE FLAP ANNUNCIATOR PANEL. | | | | | | | | |
| 2752 SWIA | 197SW 120186 | EMB EMB120ER | PWA PW118A | | | CONNECTOR | WATER CONTAM RT TE FLAP | | 12/6/97 SWIA971039 |
| | RIGHT NACELLE FLAP DEPLOYED (UNCOMMANDED) AT 210 KTS ON APPROACH TO LAX. FOUND WATER IN RIGHT NACELLE FLAP ACTUATOR CANNON PLUG. CLEANED, RECONNECTED AND CYCLED FLAPS NUMEROUS TIMES. OPS CHECKS GOOD AT THIS TIME WITH NO FAULTS NOTED. | | | | | | | | |
| 2752 COMA | 196CA 120196 | EMB EMB120RT | | | | ACTUATOR 3203001007 | FAILED RT TE FLAP | 16507 5586 | 12/21/97 COMA9710502 |
| | FLAP CONTROL FAULT WARNING. REPLACED THE RIGHT OUTBOARD FLAP ACTUATOR. | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|----------------------------|-----------------------------|------------|----------------------------|
| 3060 COMA | 266CA 120258 | EMB EMB120RT | | | | BRUSH BLOCK 7756892 | WORN RT PROP | | 12/24/97 COMA9710509 |
| RIGHT HAND PROPELLER DE-ICE FAILED. REPLACED THE BRUSH BLOCK ASSY. | | | | | | | | | |
| 3150 COMA | 263CA 120255 | EMB EMB120RT | | | | CIRCUIT BREAKER | TRIPPED COCKPIT | | 12/26/97 COMA9710507 |
| TRIM WARNING DURING TAKEOFF. AURAL WARNING CIRCUIT BREAKER WAS TRIPPED. RESET BREAKER AND SYSTEM TEST NORMAL. | | | | | | | | | |
| 3260 COMA | 258CA 120247 | EMB EMB120RT | | | | BOX CONTROL 12038594001 | MALFUNCTION LANDING GEAR | 15622 | 12/23/97 COMA9710505 |
| AFTER LANDING GEAR SELECTED UP, THE LEFT HAND MLG INDICATED INTRANSIT. REPLACED THE LANDING GEAR CONTROL BOX. | | | | | | | | | |
| 3350 COMA | 247CA 120225 | EMB EMB120RT | | | | WIRE | BROKEN CABIN | | 12/23/97 COMA9710506 |
| SOME OF THE CABIN FLOOR PATH EMERGENCY LIGHTS ARE INOP. REPAIRED BROKEN WIRE. | | | | | | | | | |
| 3350 COMA | 263CA 120255 | EMB EMB120RT | | | | LAMP 1317 | FAILED CABIN | | 12/19/97 COMA9710504 |
| LEFT OVERWING EMERGENCY LIGHT IS INOP. REPLACED LAMP. | | | | | | | | | |
| 3350 COMA | 462CA 120264 | EMB EMB120RT | | | | BATTERY D36604001 | DISCHAGED CABIN | 12221 3 | 12/24/97 COMA9710508 |
| EMERGENCY LIGHTS ARE INOP. REPLACED EMERGENCY BATTERY PACKS. | | | | | | | | | |
| 3610 COMA | 259CA 120252 | EMB EMB120RT | | | | PRESS REGULATOR 38E966A | LEAKING LT ENGINE | 16883 1 | 12/19/97 COMA9710503 |
| LEFT AIR DUCT LEAK WARNING ACTIVATED. WARNING CEASED AFTER ENGINE SHUT DOWN. REPLACED THE LEFT BLEED AIR PRESSURE REGULATOR. | | | | | | | | | |
| 2740 QXEA ***** | 491US 11156 | FOKKER F28MK4000 | | | | TRIM | MALFUNCTIONED HORIZ STAB | | 12/20/97 QXEA9700917 |
| PDX- DESCENDING THROUGH 13000 FT, FIRST OFFICER DISCONNECTED THE AUTOPILOT FOR LANDING. FELT A NOSE DOWN FORCE ON THE ELEVATOR AND ATTEMPTED TO TRIM THE PRESSURE OFF WITH STABILIZER TRIM WHEEL. ALTERNATE STAB TRIM WAS TRIED BUT IT TRIPPED CIRCUIT BREAKER. THE CIRCUIT BREAKER WAS RESET AND ALTERNATE TRIM TRIED AGAIN BUT CIRCUIT BREAKER TRIPPED A SECOND TIME. FIRST OFFICER SLOWED AIRCRAFT TO ABOUT 210 KNOTS AND CONTINUED TO FLY MANUALLY. DIRECT ROUTING TO RUNWAY REQUESTED. AIRCRAFT LANDED WITHOUT INCIDENT. AIRCRAFT DOWN FOR REPAIRS. | | | | | | | | | |
| 3350 QXEA | 452US 11105 | FOKKER F28MK1000 | | | | POWER SUPPLY 6008905 | INOPERATIVE CABIN | | 12/25/97 QXEA9700923 |
| PDX- OVERWING EMERGENCY EXIT GREEN EXIT SIGN LIGHTS INOP ON LEFT AND RIGHT SIDE. REPLACED LEFT AND RIGHT OVERWING EMERGENCY EXIT BATTERY POWER SUPPLIES, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 QXEA | 491US 11156 | FOKKER F28MK4000 | | | GRIMES 2302 | BULB 1820 | FAILED CABIN | | 12/27/97 QXEA9700933 |
| GEG - COCKPIT ENTRANCE EMERGENCY EXIT SIGN HAS MANY 28V LAMPS INOP. RELAMPED, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 QXEA | 479AU 11228 | FOKKER F28MK4000 | | | GRIMES 5515900004 | BULB MGG1055 | FAILED CABIN | | 12/28/97 QXEA9700926 |
| BOI - OVERHEAD EMERGENCY EVACUATION LIGHT INOP OVER ROW 8. INSTALLED SERVICEABLE LIGHT BULB, OPERATIONAL CHECK GOOD. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|--------------------------|------------------------|-----------|----------------------------|
| 3350 QXEA | 480AU 11229 | FOKKER F28MK4000 | | | GRIMES 5515900004 | BULB MGG1055 | FAILED CABIN | | 12/26/97 QXEA9700927 |
| GEG - EXIT SIGN ABOVE CABIN DOOR INOP. RELAMPED SIGN, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 QXEA | 480AU 11229 | FOKKER F28MK4000 | | | GRIMES 2302 | BULB 1820 | FAILED CABIN | | 12/27/97 QXEA9700928 |
| GEG - OVERHEAD AISLE EMERGENCY LIGHTS AT ROWS 12 AND 13 INOP. RELAMPED, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 QXEA | 480AU 11229 | FOKKER F28MK4000 | | | GRIMES 5515800106 | SIGN 5515900004 | INOPERATIVE CABIN | | 12/27/97 QXEA9700929 |
| GEG - EXIT SIGN AT FORWARD CABIN OVERHEAD NOT ILLUMINATED. INSTALLED SERVICEABLE EXIT SIGN, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 3350 QXEA | 486US 11237 | FOKKER F28MK4000 | | | | LIGHT | MALFUNCTIONED CABIN | | 12/27/97 QXEA9700930 |
| YEG - FLOOR PROXIMITY LIGHTS IN ROWS 1 THROUGH 6 ILLUMINATED. EMERGENCY LIGHTING SYSTEM OPERATIONAL CHECK GOOD. NO PARTS REPLACED, SYSTEM FOUND SERVICEABLE. | | | | | | | | | |
| 3350 QXEA | 486US 11237 | FOKKER F28MK4000 | | | | WIRE | BROKEN CABIN | | 12/28/97 QXEA9700931 |
| SEA - FLOOR PROXIMITY LIGHTS IN ROWS 1 THROUGH 6 SEATS A/B ARE ILLUMINATED INFLIGHT AND ON GROUND. REPAIRED BROKEN WIRE AT SEAT 6, OPERATIONAL CHECK GOOD. NO PARTS REPLACED. | | | | | | | | | |
| 3350 QXEA | 486US 11237 | FOKKER F28MK4000 | | | GRIMES 2302 | BULB 1820 | FAILED CABIN | | 12/28/97 QXEA9700932 |
| GEG - EMERGENCY EXIT SIGN ROW 8A IS INOP. RELAMPED, OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 5210 QXEA | 452US 11105 | FOKKER F28MK1000 | | | | MECHANISM | DIRTY PAX DOOR | | 12/23/97 QXEA9700922 |
| PDX- FLIGHT ATTENDANT COULD NOT OPEN PASSENGER DOOR FROM THE INSIDE, HAD TO BE OPENED FROM THE OUTSIDE. CLEANED MAIN CABIN DOOR LOCK PINS AND RECEPICLE IN DOOR. NO PARTS REPLACED. NO OTHER DEFECTS NOTED. OPERATIONAL CHECK GOOD. | | | | | | | | | |
| 2120 DALA | 733DS 193C1224 | LKHEED 10113851 | | | | ACM | REQD SERVICE NR 3 | | 12/18/97 DLL10972670 |
| NR 3 PACK OVHT AT TOUCHDOWN. CABIN FILLED WITH SMOKE AND BURNING SMELL THROUGHOUT A/C. INSPECTED NR 3 PACK, FOUND NO OIL IN NR 3 ACM. LOCKED PACK VLV OUT PER MEL. FWD TO MCO AND PLAC. | | | | | | | | | |
| 2150 DALA | 725DA 193C1162 | LKHEED 10113851 | | | | PACK 73808921 | SMOKING CABIN | 31860 | 12/22/97 DLL10972703 |
| AFTER T/O APPROX 2 MIN AFTER PACKS 1 AND 3 WERE TURNED ON, SMOKE WAS NOTICED THROUGHOUT THE A/C. ALL LAV SMOKE DET SOUNDED. PACKS AND BLEEDS WERE SHUT OFF, SMOKE DID NOT GET WORSE. A/C LANDED AT BOS 5 MIN AFTER SMOKE WAS NOTED. PUT APU ON MCO AND PERFORMED DUCT BURNOUT PER M/M RAN ENG AT PWR, OPS CK GOOD. | | | | | | | | | |
| 2780 DALA | 736DY 193C1227 | LKHEED 1011385115 | | | | COMPARATOR 472085119M | FAILED LE SLATS | | 12/24/97 DLL14972725 |
| L/E SLATS LOCKED OUT AFTER T/O, SLATS WOULD NOT RETRACT. REPLACED SLAT COMPARATOR MONITOR. | | | | | | | | | |
| 2917 DALA | 761DA 193Y1208 | LKHEED 10113853 | | | | PRESS XMITTER VT0107K | LEAKING C-HYD SYST | | 12/27/97 DLL19972732 |
| WHILE IN CRUISE, LOSS C-HYD SYSTEM BOTH QUANTITY AND PRESSURE HYD PRESS LOW LIGHT NEVER CAME ON. FOUND HYD PRESS TRANSMITTER LEAKING. REPLACED TRANSMITTER, INSPECTED C-SYSTEM FILTERS, CYCLED ALL CONTROL SURFACES AND ALL CCKECS NORMAL. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|------------------------------|---------------|------------------------------|
| 3350 DALA | 784DA 193A1038 | LKHEED 10113851 | | | | INVERTER 51066 | FAILED CABIN | | 12/18/97 DLL13972676 |
| LWR GALLEY EMERG LIGHTS INOP. REPLACED INVERTER MODULE ON BACK OF BATTERY PACK, CKS OK. | | | | | | | | | |
| 5711 DALA | 755DL 193Y1184 | LKHEED 10113853 | | | | REAR SPAR | CRACKED LT/RT WING | | 12/19/97 DLL15972698 |
| THE LT AND RT REAR SPAR UPPER CAP TO WEB ATTACH HOLES WERE OVERSIZED BEYOND REPAIRABLE LIMITS TO REMOVE CRACKS. THE REAR SPARS WERE SUBSEQUENTLY MODIFIED BY REPLACING THE INBD WEB AND UPPER SPAR CAP PER LAC S/B 093-57-215. THE WORK WAS ACCOMPLISHED PER THE S/B WITH ANY DEVIATIONS NOTED AND APPROVED PER ER/A 363289-14AD, REV A. | | | | | | | | | |
| 2611 WWMA | 234AE 340B234 | SAAB 340B | | | | SMOKE DETECTOR 72111211000 | MALFUNCTIONED CARGO COMPT | | 12/21/97 8681 WWMA9700210 |
| THE CARGO SMOKE LIGHT ILLUMINATED AFTER STARTING BOTH ENGINES. REPLACED BOTH FORWARD AND AFT CARGO SMOKE DETECTORS. | | | | | | | | | |
| 2611 WWMA | 261AE 340B261 | SAAB 340B | | | | SMOKE DETECTOR 72111211000 | MALFUNCTIONED CARGO COMPT | | 12/21/97 1470 WWMA9700209 |
| CARGO SMOKE DETECTOR WOULD NOT TEST. REPLACED THE FORWARD CARGO SMOKE DETECTOR. | | | | | | | | | |
| 2611 WWMA | 324AE 340B324 | SAAB 340B | | | | SMOKE DETECTOR | FAILED TEST LAVATORY | | 12/22/97 WWMA9700211 |
| DURING PREFLIGHT, THE LAVATORY SMOKE DETECTOR FAILED TO TEST. MAINTENANCE PERFORMED OPERATIONAL CHECKS OF THE LAVATORY SMOKE DETECTION SYSTEM AND COULD NOT DUPLICATE PROBLEM. | | | | | | | | | |
| 3350 WWMA | 309AE 340B309 | SAAB 340B | | | | LIGHT PANEL 2LA0059851 | DEFECTIVE CABIN | | 12/20/97 WWMA9700208 |
| FLIGHT ATTENDENTS EMERGENCY PANEL ARMED LIGHT DOES NOT ILLUMINATE. REPLACED WITH NEW GE85 BULB. ALSO, EMERGENCY LIGHT PANEL ABOVE SEAT 14A IS LOOSE AND FALLS OUT. REPLACED LIGHT PANEL. | | | | | | | | | |
| 3350 WWMA | 329AE 340B329 | SAAB 340B | | | | BULB GE85 | FAILED CABIN | | 12/26/97 WWMA9700214 |
| DURING PREFLIGHT, THE EMERGENCY ARM LIGHT ON THE FLIGHT ATTENDENTS PANEL FAILED TO ILLUMINATE. REPLACED BULB. | | | | | | | | | |
| 3350 WWMA | 341SB 340B341 | SAAB 340B | | | | BULB 3801BEGPL | FAILED CABIN | | 12/23/97 WWMA9700212 |
| DURING MAINTENANCE CHECK, FLOOR EMERGENCY LIGHTING AT 7BC FAILED TO ILLUMINATE. REPLACED FLOOR LAMP BULB. | | | | | | | | | |
| 5610 WWMA | 354SB 340B354 | SAAB 340B | | | | WINDSHIELD 8103732 | CRACKED RT COCKPIT | 8690 | 12/26/97 WWMA9700213 |
| DURING APPROACH, THE FIRST OFFICERS FRONT WINDSHIELD OUTER PANE CRACKED. REPLACED WINDSHIELD. | | | | | | | | | |
| 6110 | | STBROS SD360 | | HARTZL HCB5MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | 14395 4470 | 6/1/96 EY2R9600822 |
| CORROSION FOUND ON BEARING. | | | | | | | | | |
| 6110 | | STBROS SD360 | | HARTZL HCB5MP3 | | BEARING 1851T | CORRODED PROPELLER ASSY | 22514 706 | 4/1/96 EY2R9600549 |
| BEARING CORRODED. | | | | | | | | | |


***** DENOTES SIGNIFICANT OCCURRENCE

DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY (cont'd)


12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|-------------|----------------------|--|---------------------|-----------------------|----------------------|--------------------------|----------------------------|---------------|----------------------------|
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | REVERSE STOP B5162 | CORRODED PROPELLER ASSY | 2834 | 6/1/96 EY2R9600774 |
| | | CORROSION FOUND ON REVERSE STOP SCREW. | | | | | | | |
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | CYLINDER D6174 | CORRODED PROPELLER ASSY | 2834 | 6/1/96 EY2R9600775 |
| | | CYLINDER FOUND CORRODED. | | | | | | | |
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | NUT A163919 | CORRODED PROPELLER ASSY | 2834 | 6/1/96 EY2R9600776 |
| | | NUT FOUND CORRODED. | | | | | | | |
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | CYLINDER PIN A1896 | CORRODED PROPELLER ASSY | 14000 4758 | 6/1/96 EY2R9600777 |
| | | CORROSION FOUND ON CYLINDER. | | | | | | | |
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | REVERSE STOP B5162 | CORRODED PROPELLER ASSY | 2834 | 6/1/96 EY2R9600778 |
| | | CORROSION FOUND ON REVERSE STOP SCREW. | | | | | | | |
| 6110 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | CYLINDER D6174 | CORRODED PROPELLER ASSY | 2834 | 6/1/96 EY2R9600779 |
| | | CYLINDER CORRODED. | | | | | | | |
| 6110 | | SWRNGN SA226TC | | ROTOL R321482F8 | | BOLT A10210E | CORRODED PROPELLER ASSY | 11083 4352 | 9/1/96 EY2R9600942 |
| | | CORROSION FOUND ON BOLT. | | | | | | | |
| 6110 | | SWRNGN SA226TC | | ROTOL R321482F8 | | CAP SCREW 130035908 | CORRODED PROPELLER ASSY | 11083 4352 | 9/1/96 EY2R9600941 |
| | | CORROSION FOUND ON CAP SCREW. | | | | | | | |
| 6114 | | SWRNGN SA226AC | | MCAULY 4HFR34C652 | | HUB D6153C652 | CORRODED PROPELLER ASSY | 15814 2454 | 5/1/96 EY2R9600623 |
| | | HUB FOUND CORRODED. | | | | | | | |
| 6110 | | SWRNGN SA227AC | | MCAULY 4HFR34C652 | | SLIP RING D40354 | CORRODED PROPELLER ASSY | 1956 | 3/1/96 EY2R9600460 |
| | | SLIP RING FOUND CORRODED. | | | | | | | |


(End of DOMESTIC SERVICE DIFFICULTY REPORT SUMMARY)



INTERNATIONAL



SERVICE DIFFICULTY REPORT



INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY**12/28/97 - 1/3/98 ISSUE: 98-01 ZAC-326**

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|--|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|--------------------------------|------------------------|----------------------------|
| 6111 | | | | ROTOL R3526123F1 | ROTOL | CLAMP 666000361 | FAILED PROPELLER BLADE | 10/27/97 2657 | 8/18/94 AU971340 |
| (AUS) PROPELLER BLADE CLAMP FAILED AT THE LAST SPOT WELD POSITION OF THE REINFORCING STRAP. | | | | | | | | | |
| 7230 | | | PWA JT9D7R4D | | PWA | COMPRESSOR BLADE | DAMAGED 8TH & 9TH STAGES | 6896 | 8/18/94 CA941004504 |
| ***** | (CAN) AFTER TAKEOFF 300 FEET THERE WAS A LOUD EXPLOSION ACCOMPANIED BY A YAW TO THE LEFT. LEFT ENGINE EGT ANNUNCIATED IN RED. ENGINE POWER REDUCED TO IDLE. FLIGHT RETURNED & LANDED WITHOUT FURTHER INCIDENT. FOUND METAL PIECES IN UPPER LEFT BLEED VALVE SCREEN ENGINE BOROSCOPIED & REVEALED DAMAGE TO 8TH & 9TH STAGE COMPRESOR BLADES. | | | | | | | | |
| 7830 | | | PWA JT9D7R4D | | | PSEU 849704 | FAULTY THRUST REVERSERS | 8/16/94 CA941004501 | |
| (CAN) ON LANDING BOTH ENGINES STAYED IN REVERSE THRUST AT 62% N1 (WOULD NOT COME OUT OF REVERSE THRUST). BOTH ENGINES SHUT-DOWN WHEN CLEARED OF RUNWAY. AIRCRAFT TOWED TO GATE. CHECK CABLES & RIGGING BOTH ENGINES. CYCLED LEFT & RIGHT THRUST REVERSERS TEN TIMES STATIC, RAN ENGINES & CYCLED LEFT & RIGHT REVERSERS. CHANGED P.S.E.U. (PROXIMITY SWITCH ELECTRONIC UNIT). | | | | | | | | | |
| 2420 | | AEROSP ATR42300 | PWA PW120 | | SWITLIK 55901 | VOLTAGE REG 201219 | OVER VOLTAGE NR 1 INVERTER | 9/20/94 CA940930009 | |
| (CAN) OVERVOLTAGE OF NR1 STATIC INVERTER WAS REPORTED. MAINTENANCE INVESTIGATION REVEALED THAT OVERVOLTAGE WAS CAUSED BY TCAS PROCESSOR WHICH RECEIVES ITS POWER FROM THE INVERTER. ELECTRICAL ANALYSIS SHOWED THAT THE INVERTER COULD EASILY ABSORB THE LOAD BUT IT HAS TO BE LINEAR. THIS IS NOT THE CASE FOR THE PROCESSOR. PROBLEM IS CURRENTLY UNDER REVIEW FOR POSSIBLE MODIFICATION. | | | | | | | | | |
| 2121 | | AIRBUS A320211 | | | | BLOWER FAN 21200011 | SEIZED ELEC COMPTMENT | 8/18/94 CA941005503 | |
| (CAN) FLIGHT CREW REPORTED A BURNING SMELL IN THE ELECTRICAL COMPARTMENT AREA. INVESTIGATION REVEALED BLOWER FAN 20HG SEIZED. BLOWER FAN WAS REPLACED. | | | | | | | | | |
| 2121 | | AIRBUS A320211 | | | | BLOWER 3454F | INOPERATIVE AVIONIC VENT | 8/30/94 CA940928501 | |
| (CAN) VENT BLOWER FAULT LIGHT ILLUMINATED ACCOMPANIED BY SMELL OF BURNING ELECTRICS. AVIONIC VENT BLOWER REPLACED AND OPERATIONALLY CHECKED SERVICEABLE. | | | | | | | | | |
| 2752 | | AIRBUS A320212 | | | | ACTUATOR | MIS RIGGED TE FLAP ACTUATOR | 2/9/97 AU970184 | |
| (AUS) RH WING INBOARD AND OUTBOARD TRAILING EDGE FLAPS MISALIGNED - NR 2 FLAP ACTUATOR INCORRECTLY RIGGED | | | | | | | | | |
| 3230 | | AIRBUS A320211 | | | | UPLOCK 201122006 | FAILED LEFT MLG | 9/6/94 CA940928507 | |
| (CAN) LEFT LANDING GEAR WOULD NOT RETRACT AFTER TAKEOFF. RECYCLED LANDING GEAR, NO CHANGE. ECAM MESSAGE SHOWED LH MAIN WITH RED AND LDG GEAR DOORS ALL OPEN. LEFT MAIN LANDING GEAR UPLOCK ASSY CHANGED. GEAR OPERATIONALLY CHECKED SERVICEABLE | | | | | | | | | |
| 5210 | | AIRBUS A320212 | | | | FITTING | MIS RIGGED PAX/CREW DOOR | 1/17/97 AU970248 | |
| (AUS) L1 DOOR ARM/DISARM CAM WORN ALLOWING ARMING LEVER TO MOVE FROM DISARMED TO ARMED POSITION WITHOUT REMOVING THE SAFETY PIN - INVESTIGATION FOUND THAT THE BORE OF THE BALL PIN FITTING WAS NOT CENTRAL UNDER THE CAM ALLOWING THE ARMING CAM TO RIDE PAST THE SAFETY PIN | | | | | | | | | |
| 2520 | | BAG BAE146200A | LYC ALF502R5 | ROTOL R2124304 | | SEAT EXTENSION C3101031105 | CRACKED CABIN | 6/16/94 CA940929001 | |
| (CAN) SEAT EXTENSION CRACKED. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-----------------------------|-----------------------------|-----------|----------------------------|
| 2820 | | BEECH 200BEECH | PWA PT6A41 | | | FUEL LINE | BLOCKED LT ENG FUEL FEED | | 8/30/94 CA940928105 |
| (CAN) LH ENGINE BEGAN SURGING, & LOW FUEL PRESSURE LIGHT CAME ON. STANDBY BOOST PUMP TURNED ON & LIGHT WENT OUT BUT ENGINE STILL SURGING. AIRCRAFT LANDED OK. INSP FOUND A RED SHOP RAG BLOCKING FUEL FEED LINE FROM WING MAIN TANK TO NACELLE TANK. | | | | | | | | | |
| 3232 | | BOEING 727225 | PWA JT8D7B | | | VALVE 10605801 | BROKEN RT MLG DOOR INB | | 9/28/94 CA941004007 |
| (CAN) ON DEPARTURE LOST HYDRAULIC PRESSURE AFTER LANDING GEAR SELECTED UP. RH MLG INBOARD DOOR IN OPEN POSITION. RECTANGULAR 1.25 X .68 SECTION MISSING FROM A PASSAGE OF THE VALVE ASSY. POSSIBLY DUE TO GRINDING OF CASTING FLASH EXTENSION DURING MANUFACTURE. | | | | | | | | | |
| 5610 | | BOEING 72722 | PWA JT8D7B | | | SLIDING WINDOW | ARCING CO-PILOTS | | 9/7/94 CA940930201 |
| (CAN) ARCING ON THE FIRST OFFICERS SLIDING WINDOW. MOUNTING BRACKET SCREW AND NUT GROUNDING OUT. ITEMS REVERSED. PART OF MOD. | | | | | | | | | |
| 2530 | | BOEING 747238B | PWA JT9D7F | | | BASE | SHORTED GALLEY HOT CUP | | 8/17/94 CA940928504 |
| (CAN) GALLEY 1 & 2 CIRCUIT BREAKERS FOR HOT CUPS POPPED. BREAKERS RESET. CIRCUIT BREAKER PANEL HOT. HOT CUP BASE BURNT | | | | | | | | | |
| 3610 | | BOEING 747433 | PWA PW4056 | | | VALVE PRESS REG 8021701 | FAILED NR2 ENGINE | 10220 | 8/22/94 CA940928502 |
| (CAN) CONTAMINATION & DAMAGE TO WIRING & CONNECTORS IN NR 2 PYLON & UPPER FORWARD SECTION OF ENGINE. ACCUMULATION OF SKYDROL FLUID IN FORWARD STRUT BOX, STRUT DRAIN LINES CLOGGED WITH COKED HYDRAULIC FLUID. UPPER FORWARD FIRE DETECTION LOOP DAMAGED BY HEAT DISTORTION. FOUND NR 2 ENGINE PRESSURE REGULATING VALVE BODY SEPARATED FROM VALVE. SKYDROL ACCUMULATION FROM PREVIOUS THRUST REVERSER ISOLATION VALVE LEAKING, LINE WAS CHANGED AT THE TIME. PRESSURE REGULATING VALVE REPLACED. UPPER FORWARD FIRE DETECTION LOOP REPLACED & TESTED. STRUT BOX DRAIN LINES CLEARED & AREA CLEANED. SEVEN CONNECTORS & HARNESS REPLACED. HYDRAULIC LEAK & SYSTEM CHECKED ON GROUND RUN. | | | | | | | | | |
| 2550 | | BOEING 767338 | | | | WIRE | BROKEN CARGO COMPARTME | | 1/23/97 AU970202 |
| (AUS) FORWARD CARGO HOLD DRIVE SYSTEM WIRE LOCATED IN THE CARGO HOLD FLOOR AT STN 520 POWER DRIVE UNIT SEVERED - TRIPPED CIRCUIT BREAKER RESETING CAUSED A SMALL FIRE CAUSING DAMAGE TO THE WIRING AND ADJACENT INSULATION | | | | | | | | | |
| 3110 | | BOEING 767233 | PWA JT9D7R4D | | | MODULE 434093003 | SHORTED INST PANEL | | 8/24/94 CA940928503 |
| (CAN) PRIOR TO PUSH BACK SMOKE BEGAN COMING OUT OF THE INSTRUMENT PANEL. WHEEL WELL FIRE LIGHT AND ELECTRONIC COMPARTMENT LIGHTS CAME ON, ALL POWER TURNED OFF. RH GREEN AND AMBER GEAR LIGHT MODULE SHORTED. | | | | | | | | | |
| 3232 | | BOEING 767275 | PWA JT9D7R4D | | | VALVE SEQUENCE 99C513301 | INTERMITTENT RH GEAR | | 9/2/94 CA940928506 |
| (CAN) RH MLG GREEN DOWN LIGHT STAYED ON WITH GEAR HANDLE UP. EICAS MESSAGE GEAR DISAGREE DISPLAYED. DOOR AMBER LIGHT AND GEAR LIGHTS ILLUMINATED. CYCLED GEAR RETRACTION OK. | | | | | | | | | |
| 5240 | | BOEING 767275 | PWA JT9D7R4D | | | PANEL 314T323039 | MISSING RT ENG OIL SVC | | 9/6/94 CA940928505 |
| (CAN) OIL SERVICE PANEL FROM RH ENGINE MISSING AN INBOARD CORE COWL DAMAGED. LARGE HOLE JUST AFT OF OIL SRVICE PANEL AND A SMALL PUNCTURE AFT OF HOLE. | | | | | | | | | |
| 7810 | | CAMAIR 480 | ALLSN 250C* | | | EDUCTOR 41200173 | CRACKED EXHAUST | 205 | 9/27/94 CA941005006 |
| (CAN) LOOSE RIVETS CAUSED A STIFFENER TO SEPARATE FROM THE EXHUAST EDUCTOR. A NEW EDUCTOR WAS INSTALLED | | | | | | | | | |

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|--|-------------------------|---------------------|-----------------------|----------------------|---------------------------|-----------------------------|-----------|----------------------------|
| 7921 | | CAMAIR 480 | ALLSN 250C* | | | FLEX COUPLING 28010413 | CRACKED COOLER FAN DRIVE | 205 | 9/27/94 CA941005007 |
| (CAN) THE FORWARD FLEX COUPLING ON THE OIL COOLING FAN DRIVE WAS FOUND CRACKED DURING INSPECTION. | | | | | | | | | |
| 3230 | | CESSNA 172RG | LYC O360F1A6 | MCAULY B2D34C220 | CESSNA | FITTING 24130023 | CRACKED NLG ACTUATOR | 5850 | 9/29/94 CA941005002 |
| (CAN) ACTUATOR FITTING OF NLG FOUND CRACKED ON BOTH SIDES. SUBMITTER SUSPECTS THAT BOLTS WERE NOT TIGHT ENOUGH BECAUSE NUTS BOTTOMED ON THREADS. ON REASSEMBLY WITH NEW PART SUBMITTER ADDED A WASHER TO EACH NUT & BOLT. CESSNA SEB 93-8 COVERS THIS PROBLEM. | | | | | | | | | |
| 8530 | | CESSNA 172N | LYC O320H2AD | MCAULY 1C160DTM | LYC | PUSH ROD LW15315 | BENT NR4 CYL INTAKE | 636 | 8/31/94 CA940928104 |
| (CAN) ENGINE RAN ROUGH IN CRUISE FLIGHT AN UNEVENTFUL LANDING WAS ACCOMPLISHED. NR4 CYLINDER INTAKE PUSH ROD AND TUBE WERE FOUND SEVERELY BENT & OIL WAS LEAKING THROUGH BROKEN SEAL AT PUSH ROD TUBE. UPON INVESTIGATION BOTH ROCKER ARM FULCRUM NUTS WERE FOUND LOOSE & EXHAUST PUSH ROD WAS SHORTER THAN STANDARD LENGTH. | | | | | | | | | |
| 7532 | | CESSNA 208B | PWA PT6A114 | | | VALVE 312124803 | FAILED COMP BLEED | 1078 | 9/26/97 CA971003008 |
| (CAN) AIRCRAFT RETURNED TO BASE AFTER PILOT OBSERVED HIGH ITT INDICATION. AIRCRAFT WAS GROUND RUN AND ENGINE PERFORMANCE INDICATED COMPRESSOR OR COLD SECTION PROBLEM WITH THE ENGINE. ENGINE WAS GROUND RUN AGAIN WITH HEATER IN GROUND MODE WHICH USES BLEED AIR FROM THE BLEED VALVE FOR HEAT ON THE GROUND. THERE WAS NO INDICATION OF THE BLEED VALVE CLOSING AT ITS REQUIRED POWER SETTING. THE COMPRESSOR BLEED VALVE WAS REPLACED AND GROUND RUN PERFORMANCE WAS RESTORED AND THE AIRCRAFT RETURNED TO SERVICE. | | | | | | | | | |
| 2750 | | CNDAIR CL6002B19 | GE CF343A | | | FLAP | FAILED FLAP ECU | 6529 | 9/3/97 CA970922021 |
| (CAN) ON APPROACH PILOTS GOT A FLAP FAIL INDICATION WHEN THEY TRIED TO SELECT MORE THAN 8 DEGREES FLAPS. FLIGHT DID GO AROUND AND THEN LANDED FLAPLESS AND OK. FLAP ELECTRONIC CONTROL UNIT TEST CARRIED OUT AS PER FAULT MANUAL. SYSTEM RESET AND NO FAULT FOUND AFTER RESET. | | | | | | | | | |
| 8520 | | DHAV DHC3 | PWA R1340* | HAMSTD 23D40 | PWA | CAM 11768 | WORN LOBE MAIN CRANKCASE | 512 | 9/23/94 CA940930001 |
| (CAN) PILOT REPORTED ENGINE IS SOUNDING LIKE IT IS OUT OF SYNC. INVESTIGATION WAS CARRIED OUT. CAM ASSEMBLY WAS FOUND TO BE WORN AT ONE OF THE LOBES. ENGINE WAS REMOVED & SENT FOR R&O. | | | | | | | | | |
| 8530 | | DHAV DHC3 | PWA R1340* | | | CYLINDER 20578A1 | SEPARATED ENG NR 1 CYL | 611 | 9/12/97 CA970926010 |
| ***** | (CAN) THE AIRCRAFT WAS ON DESCENT, FOR SEVERAL MINUTES, WITH REDUCED POWER, THE ENGINE BACKFIRED AND QUIT. POWER OFF LANDING CARRIED OUT ON LAKE. THE ENGINE WAS RESTARTED FOR TAXIING, BUT RAN ROUGH AND WAS SHUTDOWN. INSPECTION FOUND THE NR1 CYLINDER HEAD HAD SEPARATED THROUGH THE CENTRE WITH THE ENTIRE INTAKE VALVE HOUSING. INTAKE VALVE PIECES ENTER BLOWER DIFFUSER SECTION WITH SOME PIECES FOUND IN NR5 AND NR6 CYLINDER INDUCTION PIPES. THE EXHAUST VALVE WAS ALSO BROKEN AND POUNDED INTO A TRIANGULAR SHAPE AND REMAINED IN THE CYLINDER UPPER CHAMBER. THERE WAS HEAVY METAL CONTAMINATION THROUGHOUT THE ENGINE. THE ENGINE WAS DEEMED UNREPAIRABLE AND REMOVED. | | | | | | | | |
| 7200 | | DHAV DHC6200 | PWA PT6A20 | HARTZL | PWA | ENGINE | OIL LEAK NR1 POSITION | | 9/27/94 CA941004006 |
| (CAN) DURING PRE-DESCENT CHECK THE NR1 ENGINE OIL PRESSURE WARNING LIGHT ILLUMINATED & THE OIL PRESSURE GAUGE READING DROPPED RAPIDLY. THE ENGINE WAS SHUTDOWN & THE AIRCRAFT RETURNED TO BASE. INSPECTION REVEALED THE ENGINE OIL QUANTITY WAS VERY LOW, METAL SLIVERS WERE FOUND IN THE CHIP DETECTOR, OIL FILTER SCREEN CHECKED & FOUND CLEAR. THE ENGINE WAS SPLIT & EVIDENCE OF AN OIL LEAK WAS FOUND IN THE POWER SECTION. THE ENGINE HAS BEEN REMOVED FOR REPAIR | | | | | | | | | |
| 2560 | | DHAV DHC8311 | | | | DITCHING DAM | DEPLOYED EMERGENCY EQUIP | | 2/24/97 AU970191 |
| (AUS) LH UNDERWING DITCHING DAM DEPLOYED IN FLIGHT - SEE MDR 97/0190 FURTHER INFORMATION ON SIMILAR DEFECT | | | | | | | | | |

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|--|----------------------|-------------------------|---------------------|-----------------------|----------------------|-------------------------------|----------------------------|-----------|----------------------------|
| 2560 | | DHAV DHC8311 | | | | DITCHING DAM | FAILURE EMERGENCY EQUIP | | 2/21/97 AU970190 |
| (AUS) LH DITCHING DAM INFLATED - INVESTIGATION FOUND THAT THE CAUSE WAS THE FAILURE OF THE GASKET INSTALLED IN THE DITCHING DAM ADAPTER | | | | | | | | | |
| 2750 | | DHAV DHC8102 | PWA PW120A | | | FLEX DRIVE CORE 5906989201 | FAILED TORQUE SENSOR | | 9/26/94 CA941005005 |
| (CAN) AFTER TAKEOFF FLAPS SELECTED FROM 5 DEGREES TO 0 DEGREE RESULTED IN A FLAP DRIVE CAUTION LIGHT. LIGHTS OUT WHEN FLAPS AT 3 DEGREES. FLAP SECONDARY FLEX DRIVE FAILED AT TORQUE SENSOR. | | | | | | | | | |
| 2910 | | DHAV DHC8102 | PWA PW120A | HAMSTD | | LINE 82970010633 | LEAKING LT HYD MANIFOLD | | 9/15/94 CA940930004 |
| (CAN) ON CLIMB OUT CREW NOTICED RAPID LOSS OF HYDRAULIC FLUID IN NR1 SYSTEM. HYDRAULIC PRESSURE LINE FROM LH SKID CONTROL VALVE TO THE LH HYDRAULIC PRESSURE MANIFOLD ASSY CRACKED. LINE REPLACED. | | | | | | | | | |
| 2923 | | DHAV DHC8311 | PWA PW123 | | | HANDLE 1022851 | DAMAGED BRAKE HYD PUMP | | 9/18/94 CA940929002 |
| (CAN) ON DEPARTURE WHEN GEAR SELECTED UP RH MAIN GEAR UNSAFE LIGHT AND 3 AMBER GEAR DOOR LIGHTS STAYED ON. ALTERNATE EXTENSION USED. PARKING BRAKE HAND PUMP HANDLE HAD NOT BEEN PROPERLY STOWED AND INTERFERED WITH LANDING GEAR COMPONENTS ON RETRACTION. | | | | | | | | | |
| 3246 | | DHAV DHC8102 | PWA PW120A | | BFGOODRICH 314353 | WHEEL HALF 314353 | CORRODED DRIVE LUG | | 8/28/94 CA941004001 |
| (CAN) INNER HALF HAS A CRACK IN THE BEADSEAT TANGENT POINT LOCATED APPROXIMATELY MID-WAY BETWEEN TWO DRIVE LUGS. VISUAL CORROSION IS LIFTING PAINT AT THIS SPOT. | | | | | | | | | |
| 5610 | | DHAV DHC8102 | PWA PW120A | | | WINDSHIELD NP1579016 | CRACKED COCKPIT | | 8/15/94 CA940929003 |
| (CAN) AT 24,000 FT FIRST OFFICER WINDSHIELD CRACKED OUTER PANE ONLY. | | | | | | | | | |
| 7722 | | DHAV DHC8102 | PWA PW120A | | | T6 PROBE 3038413 | SHORTED ENGINE | | 9/22/94 CA941004002 |
| (CAN) IN CRUISE ITT ROSE TO 875 DEGREES, POWER REDUCTION LOWERED TEMPERATURE TO 790 DEGREES IT THEN WENT TO 1000 DEGREES PLUS ENGINE WAS SHUTDOWN. INSPECTION FOUND TWO THERMOCOUPLES SHORTED THERMOCOUPLES WERE REPLACED. | | | | | | | | | |
| 7921 | | DHAV DHC8* | PWA PW120 | | | OIL COOLER | CRACKED NR1 ENGINE | 8641 | 9/28/94 CA941003003 |
| (CAN) IN FLIGHT THE PILOT SAW THE MAIN OIL PRESSURE FLUCTUATING. THE ENGINE WAS SECURED & AN UNEVENTFUL SINGLE ENGINE LANDING WAS MADE AT THE INTENDED DESTINATION. GROUND INSPECTION FOUND THE ENGINE NACELLE SOAKED WITH OIL AND DETERMINED A CRACKED OIL COOLER (AIRFRAME ITEM) TO BE THE CAUSE. FOLLOWING REPAIR, GROUND RUNS & CHECKS THE AIRCRAFT WAS RETURNED TO SERVICE. | | | | | | | | | |
| 7921 | | DHAV DHC8102 | PWA PW120A | | JANITROL | OIL COOLER 28E997 | CRACKED NR 1 ENG | 9975 | 9/28/94 CA941004010 |
| (CAN) NR1 ENGINE WAS SHUTDOWN IN FLIGHT DUE TO LOSS OF ENGINE OIL PRESSURE. GROUND INSPECTION REVEALED THE OIL COOLER FAILED AT A WELD IN THE CORE CAUSING LOST OF OIL. | | | | | | | | | |
| 8530 | | DOUG DC3 | PWA R183092 | | PWA | CYLINDER | CRACKED NR11 POSITION | 250 | 9/24/94 CA941004004 |
| (CAN) AIRCRAFT TOOK OFF & FLEW FOR TWENTY MINUTES WHEN NR2 ENGINE BEGAN TO RUN ROUGH. AIRCRAFT RETURNED TO BASE. INSPECTION FOUND NR11 CYLINDER HEAD CRACKED. METAL WAS FOUND IN OIL SCREEN & SUMP. SUSPECT FAILURE OF THE EXHAUST VALVE. ENGINE WILL BE SENT FOR REPAIR. | | | | | | | | | |

***** DENOTES SIGNIFICANT OCCURRENCE

INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY (cont'd)

12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326

| ATA OPER | REG. NO SERIAL NO | ACFT MAKE ACFT MODEL | ENG MAKE ENG MDL | PROP MAKE PROP MDL | COMP MFG COMP MDL | PART NAME PART NUMBER | PART COND PART LOC. | TT TSO | DIFF. DATE OPER CONT NO |
|---|---|-------------------------|---------------------|-----------------------|----------------------|----------------------------|----------------------------|-----------|----------------------------|
| 3445 | | DOUG DC932 | PWA JT8D7A | | | TCAS TRANSPONDER G99306 | SHORTED COCKPIT | | 8/17/94 CA941005502 |
| (CAN) SMOKE SEEN COMING FROM TCAS TRANSPONDER UNIT. TCAS CIRCUIT BREAKER PULLED AND SMOKE STOPPED. MAINTENANCE ACTION INVOLVED CHANGING TCAS TRANSPONDER SELECT PANEL. | | | | | | | | | |
| 3213 | | GULSTM G159 | RROYCE DART5298X | ROTOL R1844304 | GULSTM | STRUT ADAPTOR 173625 | CRACKED MLG | | 9/20/94 CA941003001 |
| (CAN) PART FOUND CRACKED ON 18 MONTH SKED NDT CHECK. | | | | | | | | | |
| 7260 | | GULSTM G159 | RROYCE DART5298E | ROTOL R1844304 | | DRIVE SHAFT 66WAY3002 | WRONG PART GEARBOX | | 9/28/94 CA941005101 |
| (CAN) AFTER MAINTENANCE, AIRCRAFT WAS ENROUTE WHEN NR1 GEARBOX LOW OIL PRESSURE LIGHT ILLUMINATED AND ENGINE WAS SHUT DOWN. AIRCRAFT RETURNED TO AIRPORT FOR MAINTENANCE. INVESTIGATION REVEALED THAT THE INCORRECT SHAFT (P/N 601017043) WAS INSTALLED. THE PROPER SHAFT FOR A WET SPLINE APPLICATION (P/N 601017096) WAS INSTALLED AND AIRCRAFT GROUND RUN SERVICEABLE. SUBMITTER SUGGESTS THAT BETTER VISUAL INDICATION THAT THE UNIT HAS BEEN MODIFIED MAY HAVE PREVENTED THIS PROBLEM. | | | | | | | | | |
| 3250 | | PIPER PA31350 | | HARTZL HCE3YR2A | | BOLT AN3H7 | SHEARED NOSE STEERING | | 9/20/94 CA941005003 |
| (CAN) NOSE STEERING U/S. 3 BOLTS SECURING STEERING ARM TO UPPER NOSE GEAR LEG FOUND SHEARED. | | | | | | | | | |
| 5751 | | PIPER PA31350 | | | PIPER 4020022 | SPAR 4019008 | CRACKED LT AILERON | 16043 | 8/2/94 CA940928107 |
| ***** | (CAN) SLIGHT FLEXING NOTICED BETWEEN LH AILERON INBOARD BEARING ATTACH BRACKET & AILERON SPAR. BRACKET REMOVAL SHOWED A 2 INCH CRACK IN AILERON SPAR. A 1" CRACK FOUND ON RH. | | | | | | | | |
| 2431 | | PIPER PA421000 | | | | CONNECTOR | MISWIRED BATT TEMP WARN | 2556 | 8/25/94 CA940930202 |
| (CAN) CONNECTORS E401 & E402 OF BATTERY TEMP WARNING SYSTEM WERE WIRED WRONG USING PINS A & B RATHER THAN A & C. | | | | | | | | | |
| 3230 | | PIPER PA42 | PWA PT6A41 | HARTZL | | RETRACT ARM 4204202 | CRACKED MAIN LDG GEAR | 4828 | 7/29/94 CA940928102 |
| (CAN) CRACK FOUND ON MLG RETRACT ARM. CRACK RUNS ACROSS INSIDE RADIUS, & ABOUT 1/16 INTO BOTH FACES. FOUND AS A RESULT OF A SPECIAL INSPECTION. | | | | | | | | | |
| 7210 | | STBROS SD330 | PWA PT6A45B | HARTZL HCB5MP3 | PWA | BEARING 3032244 | FAILED PLANETARY GEAR | 2298 | 9/27/94 CA941004008 |
| (CAN) THE BEARING ON ONE PLANET GEAR HAD PICKED UP METAL, OVERHEATED & SEIZED. | | | | | | | | | |
| (End of INTERNATIONAL SERVICE DIFFICULTY REPORT SUMMARY) | | | | | | | | | |



U.S. Department
of Transportation
**Federal Aviation
Administration**

SERVICE DIFFICULTY REPORT SUMMARY

AIR CARRIER - INDEX



The following information provides a tally of the Service Difficulty Reports (SDR's) contained in this weeks issue of the Air Carrier SDR Summary. The totals represent only a summation of the SDR's that were submitted to the FAA, Aviation Data Systems Branch, AFS-620, and processed in time for inclusion in the Summary. In the first table, the SDR's are sorted by the operator designator code and are listed in alphabetical order. The second table sorts the SDR's by the aircraft make and model. The heading at the top of each table provides a two digit Joint Aircraft System/Component (JASC) code grouping (e.g., JASC codes 1100 thru 1800 are represented by the heading labeled 11-18) which categorizes in general, the problem areas for each reported discrepancy.

The Flight Standards Service Difficulty Program objective is to achieve prompt and appropriate correction of conditions adversely affecting continued airworthiness of aeronautical products. This is accomplished by the collection of Service Difficulty and Malfunction or Defect Reports. SDR's are consolidation and collation into common data base where they are analyzed for trends, problems, and alert information. This information is then disseminated to the appropriate segments of the aviation community and to other FAA offices.

The number of SDR's submitted is not an indicator of the mechanical reliability or fitness of an air carrier's aircraft fleet and should not be used as such. The air carriers certificate holding office has the primary responsibility for planning, programming evaluations, and assessing the performance of operators. Questions regarding an air carrier's fleet performance should be directed to the appropriate Flight Standards District Office, Certificate Management Office, or Certificate Management Unit.

AIR CARRIER SUMMARY INDEX BY OPERATOR**12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326**

| OPERATOR DESIGNATOR | DISTRICT OFFICE | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------------|--------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| | AU S | 0 | 4 | 0 | 0 | 1 | 1 | 0 | 0 | 6 |
| | CA | 0 | 11 | 11 | 0 | 4 | 0 | 11 | 4 | 41 |
| | GL 03 | 0 | 0 | 0 | 0 | 0 | 25 | 0 | 0 | 25 |
| CALA | SW 09 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CKSA | GL 23 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| COMA | SO 01 | 0 | 6 | 11 | 0 | 0 | 0 | 1 | 0 | 18 |
| DALA | SO 27 | 0 | 8 | 7 | 0 | 22 | 0 | 1 | 0 | 38 |
| DHLA | SO 01 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 2 |
| FDEA | SO 25 | 0 | 2 | 1 | 0 | 0 | 0 | 2 | 0 | 5 |
| IPXA | SO 01 | 0 | 2 | 1 | 0 | 3 | 0 | 0 | 0 | 6 |
| IXXA | GL 23 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| K3HA | EA 25 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 3 |
| KT3R | WP 07 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| M8XA | NM 03 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| NWAA | GL 01 | 0 | 1 | 12 | 0 | 0 | 0 | 2 | 0 | 15 |
| QXEA | NM 09 | 0 | 3 | 9 | 0 | 4 | 1 | 0 | 0 | 17 |
| RRXA | WP 15 | 0 | 2 | 2 | 0 | 0 | 0 | 0 | 0 | 4 |
| SWIA | NM 07 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 3 |
| TC8A | GL 23 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| TSAA | WP 13 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| USAA | EA 19 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| VJ6A | SO 11 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 4 |
| VNAA | GL 07 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| W8PA | NM 03 | 0 | 1 | 5 | 0 | 44 | 0 | 0 | 0 | 50 |
| WWMA | WP 15 | 0 | 3 | 3 | 0 | 1 | 0 | 0 | 0 | 7 |
| TOTALS | | 0 | 52 | 69 | 0 | 82 | 28 | 18 | 4 | 253 |

(End of AIR CARRIER SUMMARY INDEX by OPERATOR Report)

AIR CARRIER SUMMARY INDEX by MANUFACTURER MAKE and MODEL**12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326**

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| | | 0 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 3 |
| AEROSP | ATR42300 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| AIRBUS | A320211 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 3 |
| AIRBUS | A320212 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 2 |
| BAG | BAE146200A | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | 1900C | 0 | 0 | 0 | 0 | 0 | 9 | 0 | 0 | 9 |
| BEECH | 1900D | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| BEECH | 200BEECH | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BEECH | 300BEECH | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| BOEING | 72722 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BOEING | 727225 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 4 |
| BOEING | 727225 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BOEING | 727227 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 2 |
| BOEING | 727228 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| BOEING | 72722C | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 727232 | 0 | 2 | 4 | 0 | 15 | 0 | 1 | 0 | 22 |
| BOEING | 727233 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 727247 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 72725C | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 7272D4 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| BOEING | 737230C | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 7373B7 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 4 |
| BOEING | 7373K9 | 0 | 1 | 0 | 0 | 44 | 0 | 0 | 0 | 45 |
| BOEING | 7373L9 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 7373Q8 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 747121 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 747123F | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| BOEING | 747238B | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 747433 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 747451 | 0 | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 3 |
| BOEING | 757232 | 0 | 0 | 1 | 0 | 2 | 0 | 0 | 0 | 3 |
| BOEING | 75724APF | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 | 3 |
| BOEING | 767232 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 2 |
| BOEING | 767233 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| BOEING | 767275 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 2 |
| BOEING | 767332 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| BOEING | 767338 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| CAMAIR | 480 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 2 |
| CESSNA | 172N | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |
| CESSNA | 172RG | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| CESSNA | 208B | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| CNDAIR | CL6002B19 | 0 | 4 | 4 | 0 | 0 | 0 | 1 | 0 | 9 |
| DHAV | DHC3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 2 |
| DHAV | DHC6200 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| DHAV | DHC7* | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| DHAV | DHC8* | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| DHAV | DHC8102 | 0 | 4 | 1 | 0 | 4 | 0 | 2 | 0 | 11 |
| DHAV | DHC8202 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| DHAV | DHC8311 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| DHAV | DHC8311 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| DORNER | DO328100 | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 2 |
| DOUG | B18A | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |
| DOUG | DC1040 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| DOUG | DC3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | SDR TOTALS BY FAA ATA SYSTEM CHAPTER | | | | | | | | TOTAL |
|------------------|-------------------|--------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|
| | | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | |
| DOUG | DC862F | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 2 |
| DOUG | DC863 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| DOUG | DC871F | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 3 |
| DOUG | DC8F55 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| DOUG | DC931 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 2 |
| DOUG | DC932 | 0 | 5 | 6 | 0 | 0 | 0 | 0 | 0 | 11 |
| DOUG | DC941 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 2 |
| DOUG | DC951 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| DOUG | DC982 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| DOUG | MD88 | 0 | 1 | 1 | 0 | 2 | 0 | 0 | 0 | 4 |
| EMB | EMB120ER | 0 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 3 |
| EMB | EMB120RT | 0 | 3 | 7 | 0 | 0 | 0 | 0 | 0 | 10 |
| FOKKER | F28MK1000 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 2 |
| FOKKER | F28MK4000 | 0 | 1 | 8 | 0 | 0 | 0 | 0 | 0 | 9 |
| GULSTM | G159 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 2 |
| LKHEED | 10113851 | 0 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 3 |
| LKHEED | 1011385115 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| LKHEED | 10113853 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 2 |
| PIPER | PA31350 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 2 |
| PIPER | PA42 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| PIPER | PA421000 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| SAAB | 340B | 0 | 3 | 3 | 0 | 1 | 0 | 0 | 0 | 7 |
| STBROS | SD330 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 |
| STBROS | SD360 | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 2 |
| SWRNGN | SA226AC | 0 | 0 | 0 | 0 | 0 | 7 | 0 | 0 | 7 |
| SWRNGN | SA226TC | 0 | 0 | 0 | 0 | 0 | 2 | 0 | 0 | 2 |
| SWRNGN | SA227AC | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 1 |

| AIRCRAFT MAKE | AIRCRAFT MODEL | 11-18 | 21-29 | 30-38 | 45-49 | 51-57 | 61-67 | 71-79 | 80-85 | TOTAL |
|------------------|-------------------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| TOTALS | | 0 | 52 | 69 | 0 | 82 | 28 | 18 | 4 | 253 |

(End of AIR CARRIER SUMMARY INDEX by OPERATOR Report)

THIS WEEKS PARTICIPANTS BY OPERATOR DESIGNATOR**12/28/97 To 1/3/98 ISSUE: 98-01 ZAC-326**

| <u>OPER. DESIG.</u> | <u>OPERATOR NAME</u> | <u>FAA DIST. OFF.</u> |
|--|-------------------------------------|------------------------------|
| CALA | CONTINENTAL AIRLINES INC | SW09 |
| CKSA | AMERICAN INTERNATIONAL AIRWAYS INC | GL23 |
| COMA | COMAIR INC | SO01 |
| DALA | DELTA AIR LINES INC | SO27 |
| DHLA | DHL AIRWAYS INC | SO01 |
| FDEA | FEDERAL EXPRESS CORP | SO25 |
| IPXA | UNITED PARCEL SERVICE CO | SO01 |
| IXXA | AIR TRANSPORT INTERNATIONAL LIMITED | GL23 |
| K3HA | KIWI INTERNATIONAL AIRLINES | EA25 |
| KT3R | GORDON B HAMILTON CO | WP07 |
| M8XA | MOUNTAIN AIR EXPRESS INC | NM03 |
| NWAA | NORTHWEST AIRLINES INC | GL01 |
| OXEA | HORIZON AIR INDUSTRIES INC | NM09 |
| RRXA | EMERY WORLDWIDE AIRLINES INC | WP15 |
| SWIA | SKYWEST AIRLINES INC | NM07 |
| TC8A | TRANS CONTINENTAL AIRLINES INC | GL23 |
| TSAA | ALOHA AIRLINES INC | WP13 |
| USAA | USAIR INC | EA19 |
| VJ6A | VALUJET AIRLINES INC | SO11 |
| VNAA | PSA AIRLINES INC | GL07 |
| W8PA | WESTERN PACIFIC AIRLINES INC | NM03 |
| WWMA | WINGS WEST AIRLINES INC | WP15 |
| (End of THIS WEEKS PARTICIPANTS BY OPERATOR DESIGNATOR Report) | | |

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

PREFACE

The Joint Aircraft System/Component (JASC) Code Table is a modified version of the Air Transport Association of America (ATA), Specification 100 code. It was developed by the Federal Aviation Administration's (FAA), Aviation Data Systems Branch (AFS-620). Technical support was provided by the Galaxy Scientific Corporation, and various representatives of the air carrier and general aviation community.

Over the past four years, the JASC format of the ATA Spec 100 code has gained widespread industry acceptance. In a harmonized effort, the FAA's counterparts in Australia and Canada have adopted the JASC code with only a few exceptions. Some Canadian aircraft manufacturers have also recently adopted this new standard.

This code table is constructed by using the new JASC four (4) digit code, along with an abbreviated code title. The abbreviated titles have been modified in some cases to clarify the intended use of the accompanying code. This table can be used as a quick reference chart, to assist in the coding and review of aircraft structures or systems data (i.e., Service Difficulty Report (SDR), Accident/Incident Report).

The current coding scheme used in the JASC code was introduced in May 1991, for the technical classification of SDR's. Its predecessor, the FAA aircraft system/component code, was a similar but more complex eight-digit code which was developed over 25 years ago. It was constructed around the computer technology of that period. It consisted of a four digit numerical code plus a four alpha character code to make data retrieval possible. Since that time, computer technology has advanced many fold. Reducing the code from eight to four characters simplifies coding, and in some cases, makes JASC coding match the ATA Specification 100 first three digits, which are used to identify aircraft systems. The ATA code does not reference the fourth digit, so it is free to be used for identifying components.

The JASC code aircraft structural section has increased due to problems inherent with aging aircraft. As an example, FAA code 5301 SXBD was expanded to 20 items due to the high rate of reporting in this area (8021 structural reports were received in 1989). In some instances, there was very little reporting and codes were combined into other systems if the safety impact was not significant. The overall reduction in codes has been from 568 FAA codes to 488 JASC codes, with the significant increase being in the structural area as stated earlier.

The JASC code divides the engine section into two major code groups to separate the turbine and reciprocating engines. The codes for the turbine engines are in JASC Chapter 72, Turbine/Turboprop Engine. The codes for the reciprocating engines are now exclusively found in JASC Chapter 85, Reciprocating Engine.

The other major deviation from ATA Spec 100 is in ATA section 2730, specifically involves the stall warning system. Early technology (primarily on smaller aircraft) directly linked the sensing of flight attitude to one of the components which furnished the means of manually controlling the flight attitude characteristics (elevator). Today, most large transport category aircraft utilize electronic units to sense the change in the environmental condition called stall, and use the data to influence navigation. ATA section 3410, Flight Environment Data, includes high speed warning in its code definition. Stall warning (low speed) is the reciprocal term of high speed warning, so its filing under the same code appears more logical. Thus, with the JASC code it was decided to move the stall warning system to Chapter 34 under the separate code JASC code 3418, Stall Warning System.

The FAA is continuing to pursue worldwide involvement from operators and manufacturers in addressing the need for international standardization of aircraft system/component codes. The ultimate goal is to develop a universal aircraft/component numbering standard which can be used in the manufacturer's maintenance manual, wiring diagram manual, system manuals and illustrated parts catalog. This harmonized standard must be a usable standard for the aircraft manufacturers, air carrier operators and the general aviation community.

We welcome comments and feedback regarding the possible forming of working groups to achieve this long range consideration of possibly harmonizing the ATA Specification 100 code and the JASC code. Comments may be directed to the FAA, Aviation Data Sytem Branch, AFS-620, P.O. Box 25082, Oklahoma City, OK 73125.

JOINT AIRCRAFT SYSTEM/COMPONENT CODE TABLE

JASC/ TITLE

11 PLACARDS AND MARKINGS

1100 PLACARDS AND MARKINGS

12 SERVICING

1210 FUEL SERVICING
1220 OIL SERVICING
1230 HYDRAULIC FLUID SERVICING
1240 COOLANT SERVICING

18 HELICOPTER VIBRATION

1800 HELICOPTER VIB/NOISE ANALYSIS
1810 HELICOPTER VIBRATION ANALYSIS
1820 HELICOPTER NOISE ANALYSIS

21 AIR CONDITIONING

2100 AIR CONDITIONING SYSTEM
2110 CABIN COMPRESSOR SYSTEM
2120 AIR DISTRIBUTION SYSTEM
2121 AIR DISTRIBUTION FAN
2130 CABIN PRESSURE CONTROL SYSTEM
2131 CABIN PRESSURE CONTROLLER
2132 CABIN PRESSURE INDICATOR
2133 PRESSURE REGUL/OUTFLOW VALVE
2134 CABIN PRESSURE SENSOR
2140 HEATING SYSTEM
2150 CABIN COOLING SYSTEM
2160 CABIN TEMPERATURE CONTROL SYSTEM
2161 CABIN TEMPERATURE CONTROLLER
2162 CABIN TEMPERATURE INDICATOR
2163 CABIN TEMPERATURE SENSOR
2170 HUMIDITY CONTROL SYSTEM

22 AUTO FLIGHT

2200 AUTO FLIGHT SYSTEM
2210 AUTOPILOT SYSTEM
2211 AUTOPILOT COMPUTER
2212 ALTITUDE CONTROLLER
2213 FLIGHT CONTROLLER
2214 AUTOPILOT TRIM INDICATOR
2215 AUTOPILOT MAIN SERVO
2216 AUTOPILOT TRIM SERVO
2220 SPEED-ATTITUDE CORRECT. SYSTEM
2230 AUTO THROTTLE SYSTEM
2250 AERODYNAMIC LOAD ALLEVIATING

23 COMMUNICATIONS

2300 COMMUNICATIONS SYSTEM
2310 HF COMMUNICATION SYSTEM
2311 UHF COMMUNICATION SYSTEM
2312 VHF COMMUNICATION SYSTEM
2320 DATA TRANSMISSION AUTO CALL
2330 ENTERTAINMENT SYSTEM
2340 INTERPHONE & PA SYSTEM
2350 AUDIO INTEGRATING SYSTEM
2360 STATIC DISCHARGE SYSTEM
2370 AUDIO/VIDEO MONITORING

24 ELECTRICAL POWER

2400 ELECTRICAL POWER SYSTEM
2410 ALTERNATOR-GENERATOR DRIVE
2420 AC GENERATION SYSTEM
2421 AC GENERATOR-ALTERNATOR
2422 AC INVERTER
2423 PHASE ADAPTER

24 ELECTRICAL POWER CONT'D

2424 AC REGULATOR
2425 AC INDICATING SYSTEM
2430 DC GENERATING SYSTEM
2431 BATTERY OVERHEAT WARN. SYSTEM
2432 BATTERY/CHARGER SYSTEM
2433 DC RECTIFIER-CONVERTER
2434 DC GENERATOR-ALTERNATOR
2435 STARTER-GENERATOR
2436 DC REGULATOR
2437 DC INDICATING SYSTEM
2440 EXTERNAL POWER SYSTEM
2450 AC POWER DISTRIBUTION SYSTEM
2460 DC POWER/DISTRIBUTION SYSTEM

25 EQUIPMENT/FURNISHINGS

2500 CABIN EQUIPMENT/FURNISHINGS
2510 FLIGHT COMPARTMENT EQUIPMENT
2520 PASSENGER COMPARTMENT EQUIPMENT
2530 BUFFET/GALLEYS
2540 LAVATORIES
2550 CARGO COMPARTMENTS
2551 AGRICULTURAL SPRAY SYSTEM
2560 EMERGENCY EQUIPMENT
2561 LIFE JACKET
2562 EMERGENCY LOCATOR BEACON
2563 PARACHUTE
2564 LIFE RAFT
2565 ESCAPE SLIDE
2570 ACCESSORY COMPARTMENT
2571 BATTERY BOX STRUCTURE
2572 ELECTRONIC SHELF SECTION

26 FIRE PROTECTION

2600 FIRE PROTECTION SYSTEM
2610 DETECTION SYSTEM
2611 SMOKE DETECTION
2612 FIRE DETECTION
2613 OVERHEAT DETECTION
2620 EXTINGUISHING SYSTEM
2621 FIRE BOTTLE, FIXED
2622 FIRE BOTTLE, PORTABLE

27 FLIGHT CONTROLS

2700 FLIGHT CONTROL SYSTEM
2701 CONTROL COLUMN SECTION
2710 AILERON CONTROL SYSTEM
2711 AILERON TAB CONTROL SYSTEM
2720 RUDDER CONTROL SYSTEM
2721 RUDDER TAB CONTROL SYSTEM
2722 RUDDER ACTUATOR
2730 ELEVATOR CONTROL SYSTEM
2731 ELEVATOR TAB CONTROL SYSTEM
2740 STABILIZER CONTROL SYSTEM
2741 STABILIZER POSITION INDICATING
2742 STABILIZER ACTUATOR
2750 TE FLAP CONTROL SYSTEM
2751 TE FLAP POSITION IND. SYSTEM
2752 TE FLAP ACTUATOR
2760 DRAG CONTROL SYSTEM
2761 DRAG CONTROL ACTUATOR
2770 GUST LOCK/DAMPER SYSTEM
2780 LE FLAP CONTROL SYSTEM
2781 LE FLAP POSITION IND. SYSTEM
2782 LE FLAP ACTUATOR

28 FUEL

2800 AIRCRAFT FUEL SYSTEM
2810 FUEL STORAGE
2820 ACFT FUEL DISTRIB. SYSTEM
2821 ACFT FUEL FILTER/STRAINER
2822 FUEL BOOST PUMP
2823 FUEL SELECTOR/SHUTOFF VALVE
2824 FUEL TRANSFER VALVE
2830 FUEL DUMP SYSTEM
2840 ACFT FUEL INDICATING
2841 FUEL QUANTITY INDICATOR
2842 FUEL QUANTITY SENSOR
2843 FUEL TEMPERATURE INDICATING
2844 FUEL PRESSURE INDICATOR

29 HYDRAULIC POWER

2900 HYDRAULIC POWER SYSTEM
2910 HYDRAULIC, MAIN SYSTEM
2911 HYDRAULIC POWER-ACCUMULATOR-MAIN
2912 HYDRAULIC FILTER-MAIN SYSTEM
2913 HYDRAULIC PUMP. ELECT-ENG.-MAIN
2914 HYDRAULIC HANDPUMP-MAIN
2915 HYDRAULIC PRESSURE RELIEF VLV-MAIN
2916 HYDRAULIC RESERVOIR-MAIN
2917 HYDRAULIC PRESSURE REGULATOR-MAIN
2920 HYDRAULIC, AUXILIARY SYSTEM
2921 HYDRAULIC ACCUMULATOR-AUXILIARY
2922 HYDRAULIC FILTER-AUXILIARY
2923 HYDRAULIC PUMP-AUXILIARY
2925 HYDRAULIC PRESSURE RELIEF-AUXILIARY
2926 HYDRAULIC RESERVOIR-AUXILIARY
2927 HYDRAULIC PRESSURE REGULATOR-AUX.
2930 HYDRAULIC SYSTEM INDICATING
2931 HYDRAULIC PRESSURE INDICATOR
2932 HYDRAULIC PRESSURE SENSOR
2933 HYDRAULIC QUANTITY INDICATOR
2934 HYDRAULIC QUANTITY SENSOR

30 ICE AND RAIN PROTECTION

3000 ICE/RAIN PROTECTION SYSTEM
3010 AIRFOIL ANTI/DE-ICE SYSTEM
3020 AIR INTAKE ANTI/DE-ICE SYSTEM
3030 PITOT/STATIC ANTI-ICE SYSTEM
3040 WINDSHIELD/DOOR RAIN/ICE REMOVAL
3050 ANTENNA/RADOME ANTI-ICE/DE-ICE SYSTEM
3060 PROP/ROTOR ANTI-ICE/DE-ICE SYSTEM
3070 WATER LINE ANTI-ICE SYSTEM
3080 ICE DETECTION

31 INSTRUMENTS

3100 INDICATING/RECORDING SYSTEM
3110 INSTRUMENT PANEL
3120 INDEPENDENT INSTRUMENTS (CLOCK, ETC.)
3130 DATA RECORDERS (FLT/MAINT)
3140 CENTRAL COMPUTERS (EICAS)
3150 CENTRAL WARNING
3160 CENTRAL DISPLAY
3170 AUTOMATIC DATA

32 LANDING GEAR

3200 LANDING GEAR SYSTEM
3201 LANDING GEAR/WHEEL FAIRING
3210 MAIN LANDING GEAR
3211 MAIN LANDING GEAR ATTACH SECTION
3212 EMERGENCY FLOTATION SECTION
3213 MAIN LANDING GEAR STRUT/AXLE/TRUCK
3220 NOSE/TAIL LANDING GEAR
3221 NOSE/TAIL LANDING GEAR ATTACH SECTION
3222 NOSE/TAIL LANDING GEAR STRUT/AXLE
3230 LANDING GEAR RETRACT/EXT. SYSTEM
3231 LANDING GEAR DOOR RETRACT SECTION
3232 LANDING GEAR DOOR ACTUATOR
3233 LANDING GEAR ACTUATOR
3234 LANDING GEAR SELECTOR
3240 LANDING GEAR BRAKE SYSTEM
3241 BRAKE ANTI-SKID SECTION
3242 BRAKE
3243 MASTER CYL/BRAKE VALVE
3244 TIRE
3245 TIRE TUBE
3246 WHEEL/SKI/FLOAT
3250 LANDING GEAR STEERING SYSTEM
3251 STEERING UNIT
3252 SHIMMY DAMPER
3260 LANDING GEAR POSITION & WARNING
3270 AUXILIARY GEAR (TAIL SKID)

33 LIGHTS

3300 LIGHTING SYSTEM
3310 FLIGHT COMPARTMENT LIGHTING
3320 PASSENGER COMPARTMENT LIGHTING
3330 CARGO COMPARTMENT LIGHTING
3340 EXTERIOR LIGHTING
3350 EMERGENCY LIGHTING

34 NAVIGATION

3400 NAVIGATION SYSTEM
3410 FLIGHT ENVIRONMENT DATA
3411 PITOT/STATIC SYSTEM
3412 OUTSIDE AIR TEMP. IND./SENSOR
3413 RATE OF CLIMB INDICATOR
3414 AIRSPEED/MACH INDICATING
3415 HIGH SPEED WARNING
3416 ALTIMETER, BAROMETRIC/ENCODER

34 NAVIGATION CONT'D

3417 AIR DATA COMPUTER
3418 STALL WARNING SYSTEM
3420 ATTITUDE AND DIRECTION DATA SYSTEM
3421 ATTITUDE GYRO & IND. SYSTEM
3422 DIRECTIONAL GYRO & IND. SYSTEM
3423 MAGNETIC COMPASS
3424 TURN & BANK/RATE OF TURN INDICATOR
3425 INTEGRATED FLT. DIRECTOR SYSTEM
3430 LANDING & TAXI AIDS
3431 LOCALIZER/VOR SYSTEM
3432 GLIDE SLOPE SYSTEM
3433 MICROWAVE LANDING SYSTEM
3434 MARKER BEACON SYSTEM
3435 HEADS UP DISPLAY SYSTEM
3436 WIND SHEAR DETECTION SYSTEM
3440 INDEPENDENT POS. DETERMINING SYSTEM
3441 INERTIAL GUIDANCE SYSTEM
3442 WEATHER RADAR SYSTEM
3443 DOPPLER SYSTEM
3444 GROUND PROXIMITY SYSTEM
3445 AIR COLLISION AVOIDANCE SYSTEM (TCAS)
3446 NON RADAR WEATHER SYSTEM
3450 DEPENDENT POSITION DETERMINING SYSTEM
3451 DME/TACAN SYSTEM
3452 ATC TRANSPONDER SYSTEM
3453 LORAN SYSTEM
3454 VOR SYSTEM
3455 ADF SYSTEM
3456 OMEGA NAVIGATION SYSTEM
3457 GLOBAL POSITIONING SYSTEM
3460 FLIGHT MANAGE. COMPUTING SYSTEM

35 OXYGEN

3500 OXYGEN SYSTEM
3510 CREW OXYGEN SYSTEM
3520 PASSENGER OXYGEN SYSTEM
3530 PORTABLE OXYGEN SYSTEM

36 PNEUMATIC

3600 PNEUMATIC SYSTEM
3610 PNEUMATIC DISTRIBUTION SYSTEM
3620 PNEUMATIC INDICATING SYSTEM

37 VACUUM

3700 VACUUM SYSTEM
3710 VACUUM DISTRIBUTION SYSTEM
3720 VACUUM INDICATING SYSTEM

38 WATER/WASTE

3800 WATER & WASTE SYSTEM
3810 POTABLE WATER SYSTEM
3820 WASH WATER SYSTEM
3830 WASTE DISPOSAL SYSTEM
3840 AIR SUPPLY (WATER PRESS. SYSTEM)

45 CENTRAL MAINT. SYSTEM

4500 CENTRAL MAINT. COMPUTER

49 AIRBORNE AUXILIARY POWER

4900 AIRBORNE APU SYSTEM
4910 APU COWLING/CONTAINMENT
4920 APU CORE ENGINE
4930 APU ENGINE FUEL & CONTROL
4940 APU START/IGNITION SYSTEM
4950 APU BLEED AIR SYSTEM
4960 APU CONTROLS
4970 APU INDICATING SYSTEM
4980 APU EXHAUST SYSTEM
4990 APU OIL SYSTEM

51 STANDARD PRACTICES/STRUCTURES

5100 STANDARD PRACTICES/STRUCTURES
5101 AIRCRAFT STRUCTURES
5102 BALLOON REPORTS

52 DOORS

5200 DOORS
5210 PASSENGER/CREW DOORS
5220 EMERGENCY EXIT
5230 CARGO/BAGGAGE DOORS
5240 SERVICE DOORS
5241 GALLEY DOORS
5242 E/E COMPARTMENT DOORS
5243 HYDRAULIC COMPARTMENT DOORS
5244 ACCESSORY COMPARTMENT DOORS
5245 AIR CONDITIONING COMPART. DOORS
5246 FLUID SERVICE DOORS

5247 APU DOORS
5248 TAIL CONE DOORS
5250 FIXED INNER DOORS
5260 ENTRANCE STAIRS
5270 DOOR WARNING SYSTEM
5280 LANDING GEAR DOORS

53 FUSELAGE

5300 FUSELAGE STRUCTURE (GENERAL)
5301 AERIAL TOW EQUIPMENT
5302 ROTORCRAFT TAIL BOOM
5310 FUSELAGE MAIN STRUCTURE
5311 FUSELAGE MAIN FRAME
5312 FUSELAGE MAIN BULKHEAD
5313 FUSELAGE MAIN LONGERON/STRINGER
5314 FUSELAGE MAIN KEEL
5315 FUSELAGE MAIN FLOOR BEAM
5320 FUSELAGE MISCELLANEOUS STRUCTURE
5321 FUSELAGE FLOOR PANEL
5322 FUSELAGE INTERNAL MOUNT STRUCTURE
5323 FUSELAGE INTERNAL STAIRS
5324 FUSELAGE FIXED PARTITIONS
5330 FUSELAGE MAIN PLATE/SKIN
5340 FUSELAGE MAIN ATTACH FITTINGS
5341 WING ATTACH FITTINGS (ON FUSELAGE)
5342 STABILIZER ATTACH FITTINGS
5343 LANDING GEAR ATTACH FITTINGS
5344 FUSELAGE DOOR HINGES
5345 FUSELAGE EQUIPMENT ATTACH FITTINGS
5346 POWERPLANT ATTACH FITTINGS
5347 SEAT/CARGO ATTACH FITTINGS
5350 FUSELAGE AERODYNAMIC FAIRINGS

54 NACELLES/PYLONS

5400 NACELLE/PYLON STRUCTURE
5410 MAIN FRAME (ON NACELLE/PYLON)
5411 FRAME/SPAR/RIB(NACELLE/PYLON)
5412 BULKHEAD/FIREWALL (NAC/PYLON)
5413 LONGERON/STRINGER (NAC/PYLON)
5414 PLATE SKIN (NAC/PYLONS)
5415 ATTACH FITTINGS (NAC/PYLON)

55 STABILIZERS

5500 EMPENNAGE STRUCTURE
5510 HORIZONTAL STABILIZER STRUCTURE
5511 HORIZONTAL STABILIZER SPAR/RIB
5512 HORIZONTAL STABILIZER PLATE/SKIN
5513 HORIZONTAL STABILIZER TAB STRUCTURE
5520 ELEVATOR STRUCTURE

55 STABILIZERS CONT'D

5521 ELEVATOR SPAR/RIB STRUCTURE
5522 ELEVATOR PLATES/SKIN STRUCTURE
5523 ELEVATOR TAB STRUCTURE
5530 VERTICAL STABILIZER STRUCTURE
5531 VERTICAL STABILIZER SPAR/RIB STRUCTURE
5532 VERTICAL STABILIZER PLATES/SKIN
5533 VENTRAL STRUCTURE (ON VERT. STAB)
5540 RUDDER STRUCTURE
5541 RUDDER SPAR/RIB STRUCTURE
5542 RUDDER PLATE/SKIN STRUCTURE
5543 RUDDER TAB STRUCTURE
5550 EMPENNAGE FLT. CONT. ATTACH FITTING
5551 HORIZONTAL STABILIZER ATTACH FITTING
5552 ELEVATOR/TAB ATTACH FITTINGS
5553 VERT. STAB. ATTACH FITTINGS
5554 RUDDER/TAB ATTACH FITTINGS

56 WINDOWS

5600 WINDOW/WINDSHIELD SYSTEM
5610 FLIGHT COMPARTMENT WINDOWS
5620 PASSENGER COMPARTMENT WINDOWS
5630 DOOR WINDOWS
5640 INSPECTION WINDOWS

57 WINGS

5700 WING STRUCTURE
5710 WING MAIN FRAME STRUCTURE
5711 WING SPAR STRUCTURE
5712 WING RIB STRUCTURE
5713 WING LONGERON/STRINGER
5714 WING CENTER BOX
5720 WING MISCELLANEOUS STRUCTURE
5730 WING PLATES/SKINS
5740 WING ATTACH FITTINGS
5741 WING, FUSELAGE ATTACH FITTINGS
5742 WING, NAC/PYLON ATTACH FITTINGS
5743 WING, LANDING GEAR ATTACH FITTINGS
5744 CONTROL SURFACE ATTACH FITTINGS
5750 WING CONTROL SURFACE STRUCTURE
5751 AILERON STRUCTURE
5752 AILERON TAB STRUCTURE
5753 TE FLAP STRUCTURE
5754 LEADING EDGE DEVICE STRUCTURE
5755 SPOILER STRUCTURE

61 PROPELLERS/PROPULSORS

6100 PROPELLER SYSTEM
6110 PROPELLER ASSEMBLY
6111 PROPELLER BLADE SECTION
6112 PROPELLER DE-ICE BOOT SECTION
6113 PROPELLER SPINNER SECTION
6114 PROPELLER HUB SECTION
6120 PROPELLER CONTROL SYSTEM
6121 PROPELLER SYNCHRONIZER SECTION
6122 PROPELLER GOVERNOR
6123 PROPELLER FEATHERING/REVERSING
6130 PROPELLER BRAKING
6140 PROPELLER INDICATING SYSTEM

62 MAIN ROTOR

6200 MAIN ROTOR SYSTEM
6210 MAIN ROTOR BLADES
6220 MAIN ROTOR HEAD
6230 MAIN ROTOR MAST/SWASHPLATE
6240 MAIN ROTOR INDICATING SYSTEM

63 MAIN ROTOR DRIVE

6300 MAIN ROTOR DRIVE SYSTEM
6310 ENGINE/TRANSMISSION COUPLING
6320 MAIN ROTOR GEARBOX
6321 MAIN ROTOR BRAKE
6322 ROTORCRAFT COOLING FAN SYSTEM
6330 MAIN ROTOR TRANSMISSION MOUNT
6340 ROTOR DRIVE INDICATING SYSTEM

64 TAIL ROTOR

6400 TAIL ROTOR SYSTEM
6410 TAIL ROTOR BLADE
6420 TAIL ROTOR HEAD
6440 TAIL ROTOR INDICATING SYSTEM

65 TAIL ROTOR DRIVE

6500 TAIL ROTOR DRIVE SYSTEM
6510 TAIL ROTOR DRIVE SHAFT
6520 TAIL ROTOR GEARBOX
6540 TAIL ROTOR DRIVE INDICATING SYSTEM

67 ROTORS FLIGHT CONTROL

6700 ROTORCRAFT FLIGHT CONTROL
6710 MAIN ROTOR CONTROL
6711 TILT ROTOR FLIGHT CONTROL
6720 TAIL ROTOR CONTROL SYSTEM
6730 ROTORCRAFT SERVO SYSTEM

71 POWERPLANT

7100 POWERPLANT SYSTEM
7110 ENGINE COWLING SYSTEM
7111 COWL FLAP SYSTEM
7112 ENGINE AIR BAFFLE SECTION
7120 ENGINE MOUNT SECTION
7130 ENGINE FIRESEALS
7160 ENGINE AIR INTAKE SYSTEM
7170 ENGINE DRAINS

72 TURBINE/TURBOPROP ENGINE

7200 ENGINE (TURBINE/TURBOPROP)
7210 TURBINE ENGINE REDUCTION GEAR
7220 TURBINE ENGINE AIR INLET SECTION
7230 TURBINE ENGINE COMPRESSOR SECTION
7240 TURBINE ENGINE COMBUSTION SECTION
7250 TURBINE SECTION
7260 TURBINE ENGINE ACCESSORY DRIVE
7261 TURBINE ENGINE OIL SYSTEM
7270 TURBINE ENGINE BYPASS SECTION

73 ENGINE FUEL & CONTROL

7300 ENGINE FUEL & CONTROL
7310 ENGINE FUEL DISTRIBUTION
7311 ENGINE FUEL-OIL COOLER
7312 FUEL HEATER
7313 FUEL INJECTOR NOZZLE
7314 ENGINE FUEL PUMP
7320 FUEL CONTROLLING SYSTEM
7321 FUEL CONTROL/ELECTRONIC
7322 FUEL CONTROL/CARBURETOR
7323 TURBINE GOVERNOR
7324 FUEL DIVIDER
7330 ENGINE FUEL INDICATING SYSTEM
7331 FUEL FLOW INDICATING
7332 FUEL PRESSURE INDICATING
7333 FUEL FLOW SENSOR
7334 FUEL PRESSURE SENSOR

74 IGNITION

7400 IGNITION SYSTEM
7410 IGNITION POWER SUPPLY
7411 LOW TENSION COIL
7412 EXCITER
7413 INDUCTION VIBRATOR
7414 MAGNETO/DISTRIBUTOR
7420 IGNITION HARNESS (DISTRIBUTION)
7421 SPARK PLUG/IGNITER
7430 IGNITION SWITCHING

75 AIR

7500 ENGINE BLEED AIR SYSTEM
7510 ENGINE ANTI-ICING SYSTEM
7520 ENGINE COOLING SYSTEM
7530 COMPRESSOR BLEED CONTROL
7531 COMPRESSOR BLEED GOVERNOR
7532 COMPRESSOR BLEED VALVE
7540 BLEED AIR INDICATING SYSTEM

76 ENGINE CONTROLS

7600 ENGINE CONTROLS
7601 ENGINE SYNCHRONIZING
7602 MIXTURE CONTROL
7603 POWER LEVER
7620 ENGINE EMERGENCY SHUTDOWN SYSTEM

77 ENGINE INDICATING

7700 ENGINE INDICATING SYSTEM
7710 POWER INDICATING SYSTEM
7711 ENGINE PRESSURE RATIO (EPR)
7712 ENGINE BMEP/TORQUE INDICATING
7713 MANIFOLD PRESSURE (MP) INDICATING
7714 ENGINE RPM INDICATING SYSTEM
7720 ENGINE TEMP. INDICATING SYSTEM
7721 CYLINDER HEAD TEMP (CHT) INDICATING
7722 ENG. EGT/TIT INDICATING SYSTEM
7730 ENGINE IGNITION ANALYZER SYSTEM
7731 ENGINE IGNITION ANALYZER
7732 ENGINE VIBRATION ANALYZER
7740 ENGINE INTEGRATED INSTRUMENT SYSTEM

78 ENGINE EXHAUST

7800 ENGINE EXHAUST SYSTEM
7810 ENGINE COLLECTOR/TAILOPIPE/NOZZLE
7820 ENGINE NOISE SUPPRESSOR
7830 THRUST REVERSER

79 ENGINE OIL

7900 ENGINE OIL SYSTEM (AIRFRAME)
7910 ENGINE OIL STORAGE (AIRFRAME)
7920 ENGINE OIL DISTRIBUTION (AIRFRAME)
7921 ENGINE OIL COOLER
7922 ENGINE OIL TEMP. REGULATOR
7923 OIL SHUTOFF VALVE
7930 ENGINE OIL INDICATING SYSTEM
7931 ENGINE OIL PRESSURE
7932 ENGINE OIL QUANTITY
7933 ENGINE OIL TEMPERATURE

80 STARTING

8000 ENGINE STARTING SYSTEM
8010 ENGINE CRANKING
8011 ENGINE STARTER
8012 ENGINE START VALVES/CONTROLS

81 TURBOCHARGING

8100 EXHAUST TURBINE SYSTEM (RECIP)
8110 POWER RECOVERY TURBINE (RECIP)
8120 EXHAUST TURBOCHARGER

82 WATER INJECTION

8200 WATER INJECTION SYSTEM

83 ACCESSORY GEARBOXES

8300 ACCESSORY GEARBOXES

85 RECIPROCATING ENGINE

8500 ENGINE (RECIPROCATING)
8510 RECIPROCATING ENGINE FRONT SECTION
8520 RECIPROCATING ENGINE POWER SECTION

8530 RECIPROCATING ENGINE CYLINDER SECTION
8540 RECIPROCATING ENGINE REAR SECTION
8550 RECIPROCATING ENGINE OIL SYSTEM

MECHANICS CREED

UPON MY HONOR I swear that I shall hold in sacred trust the rights and privileges conferred upon me as a certified mechanic. Knowing full well that the safety and lives of others are dependent upon my skill and judgment, I shall never knowingly subject others to risks which I would not be willing to assume for myself, or for those dear to me.

IN DISCHARGING this trust, I pledge myself never to undertake work or approve work which I feel to be beyond the limits of my knowledge; nor shall I allow any non-certificated superior to persuade me to approve aircraft or equipment as airworthy against my better judgment; nor shall I permit my judgment to be influenced by money or other personal gain; nor shall I pass as airworthy aircraft or equipment about which I am in doubt, either as a result of direct inspection or uncertainty regarding the ability of others who have worked on it to accomplish their work satisfactorily.

I REALIZE the grave responsibility which is mine as a certified airman, to exercise my judgment on the airworthiness of aircraft and equipment. I, therefore, pledge unyielding adherence to these precepts for the advancement of aviation and for the dignity of my vocation.